

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

Initial Report  Final Report

Name of Company	Plains Pipeline, LP	Contact	Daniel Bryant
Address	P.O. Box 3119 - Midland, Tx 79702	Telephone No.	(432) 557-5865
Facility Name	Zia Grizzell 4" Idled Line	Facility Type	Pipeline

Surface Owner	Apache Corporation	Mineral Owner		Lease No.	
---------------	--------------------	---------------	--	-----------	--

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	8	22S	37E					Lea

75'

Latitude N 32° 24' 10.7" Longitude W 103° 10' 38.7"

#### NATURE OF RELEASE

Type of Release	Sour Crude Oil	Volume of Release	40 bbls	Volume Recovered	30 bbls
Source of Release	4" steel idled line	Date and Hour of Occurrence	09/05/2005 10:30	Date and Hour of Discovery	09/05/2005 11:00
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Gary Wink		
By Whom?	Camille Reynolds	Date and Hour	09/05/2005 14:50		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:			

Stamp: 31-12345678  
Stamp: 09/05/2005 14:50  
Stamp: Gary Wink

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Recent pipeline work caused a collar to break on the idled Zia Grizzell 4" steel pipeline. Line was cut and capped to mitigate the release. Due to the line being idled at time of release, the pressure of the line was 0 lbs and had no throughput on the pipeline. The gravity of the crude oil is 37.1 @ 65°. H<sub>2</sub>S content is <10 ppm. Line depth is approximately 2.5' at the release source.

Describe Area Affected and Cleanup Action Taken.\*

Visible staining from the pipeline release measured 45' X 24' yielding 1,080 ft<sup>2</sup>. Impacted soil will be remediated per NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Daniel Bryant</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Daniel Bryant	Approved by District Supervisor: <i>[Signature]</i>	
Title: Environmental R/C Specialist	Approval Date: 12.21.06	Expiration Date: 3.21.06
E-mail Address: dmbryant@paalp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/9/05	Phone: (432) 557-5865	

\* Attach Additional Sheets If Necessary

Facility - APAC0635550008  
Incident - APAC0635550101  
application - APAC0635550263  
RP# 1156