

OK CW -

011

1121

**XTO ENERGY
EMSU "B"
INJECTION HEADER LEAK
Near Well EMSU "B" #906
Unit H, Sect. 23, T. 20 S., R. 36 E.
GPS: 32 33' 35" N 103 19' 03" W**

CLOSURE



**Prepared by
Eddie Seay Consulting
December 2006**



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON
Governor
Joanna Prukop
Cabinet Secretary

Mark E. Fesmire, P.E.
Director
Oil Conservation Division

12/29/2006

Eddie Seay Consulting
On behalf of XTO Energy
601 W. Illinois
Hobbs, NM 88242

Re: EMSU "B" #906 Leak

Dear Eddie:

New Mexico Oil Conservation Division (OCD) personnel reviewed the closure report submitted by Eddie Seay Consulting on behalf of XTO Energy (XTO) for the site referenced above. The closure is hereby approved according to information provided.

Please be advised that OCD approval does not relieve XTO of liability should operations result in contamination of surface water, groundwater, or the environment. In addition, OCD approval does not relieve XTO of responsibility for compliance with other federal, state or local laws and or regulations.

If you have any questions or need assistance please write or call: 505-393-6161 ext. 102, or e-mail chris.williams@state.nm.us.

Sincerely,

Chris Williams
NMOCD District1 Supervisor

December 26, 2006

NMOCD Environmental
ATTN: Larry Johnson
1625 N. French Drive
Hobbs, NM 88240

RE: XTO Energy
EMSU "B" #906 Leak

Mr. Johnson:


XTO has completed the excavation phase of this remediation and testing. We are within guidelines for closing and would like to backfill with clean soil, level, contour and seed.

XTO excavated approximately 1924 cu. yds. of dirt and hauled it to Sundance Disposal, an OCD approved facility. The clean soil will come from a site just North, off Cooper Ranch.

Whenever we get approval, we will backfill as approved and send a final report.

Find enclosed photos, analytical and map of site. If you have any questions, please call.

Sincerely,

A handwritten signature in black ink, appearing to read "Eddie W. Seay", with a long, sweeping underline that extends to the right.

Eddie W. Seay, Agent
Eddie Seay Consulting
601 W. Illinois
Hobbs, NM 88242
(505)392-2236
seay04@leaco.net

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company XTO Energy	Contact Gene Hudson
Address Box 700 Eunice NM 88231	Telephone No. 441-1634
Facility Name EMSU "B" 90'	Facility Type Injection
Surface Owner J. Cooper	Mineral Owner XTO
Lease No.	

1121

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	23	20	36					Lea

Latitude **32° 33' 35"** Longitude **103° 19' 03"**

NATURE OF RELEASE

Type of Release Injection water some oil	Volume of Release 300 bbls	Volume Recovered 200 bbls
Source of Release Injection Header	Date and Hour of Occurrence 11/10	Date and Hour of Discovery 11/10
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary Wink	
By Whom? David Paschall	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*
Injection line at header split. approx 300 bbls released. Valve was shut, approx 200 bbls vacuumed up. Repaired line.


Describe Area Affected and Cleanup Action Taken.*
Approximately 150 x 50 area in sand dune area. water settled in low area. vacuumed up as much as possible. let dry & remediate per plan.


I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.


Signature: Eddie W Seay		OIL CONSERVATION DIVISION	
Printed Name: Eddie W Seay		Approved by District Supervisor:	
Title: Agent		Approval Date:	Expiration Date:
E-mail Address: seay.04@leaso.net		Conditions of Approval:	
Date: 11/13/06 Phone: 392-2236		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary











CARDINAL LABORATORIES, INC.

2111 Beechwood, Abilene, TX 79603 101 East Marland, Hobbs, NM 88240
(915) 673-7001 Fax (915) 673-7020 (505) 393-2326 Fax (505) 393-2476

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

Page ____ of ____

Company Name: Edilio Sam Casarillo		BILL TO		ANALYSIS REQUEST		
Project Manager: Edilio Sam Casarillo		P.O. #:				
Address: Lot 1 W Fillmore		Company:				
City: Hobbs		Attn:				
State: NM Zip: 88242		Address:				
Phone #: 2.2236 Fax #: 2.6849		City:				
Project #: XTO Project Owner: XTO		State:				
Project Name: XTO 906 Haddon		Phone #:				
Project Location: Monarch		Zip:				
Sampler Name: Edilio Sam Casarillo		Fax #:				
FOR LAB USE ONLY		PRESERV		SAMPLING		
Lab I.D.	Sample I.D.	(G)RAB OR (C)OMP	# CONTAINERS	MATRIX	DATE	TIME
H11867-1	906-1	<input checked="" type="checkbox"/>	1	GROUNDWATER	12/5	4:25
-2	906-2	<input checked="" type="checkbox"/>	1	WASTEWATER	12/5	4:20
				SOIL		
				CRUDE OIL		
				SLUDGE		
				OTHER:		
				ACID/BASE:		
				ICE / COOL		
				OTHER:		

PLEASE NOTE: Liability and Damages: Cardinal's liability and client's exclusive remedy for any claim arising whether based in contract or tort, shall be limited to the amount paid by the client for the analyses. All claims including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within 30 days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise.

Terms and Conditions: Interest will be charged on all accounts more than 30 days past due at the rate of 24% per annum from the original date of invoice, and all costs of collections, including attorney's fees.

Sampler Relinquished: **Edilio Sam Casarillo**
Date: **12/5** Time: **5:05**

Received By: **[Signature]**
Date: **12/5** Time: **4:20**

Delivered By: (Circle One)
Sampler - UPS - Bus - Other: Other

Sample Condition
Cool Intact
Yes No

CHECKED BY: **[Signature]** (Initials) **AS**

REMARKS:
1 - Bottom W
2 - Bottom E
ASAP

† Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476.



CARDINAL LABORATORIES, INC.

2111 Beechwood, Abilene, TX 79603 101 East Marland, Hobbs, NM 88240
(915) 673-7001 Fax (915) 673-7020 (505) 393-2326 Fax (505) 393-2476

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

ANALYSIS REQUEST

BILL TO

Company Name: Eddie Seay Consulting

Project Manager: Eddie Seay

Address: 1001 W. T.M. Blvd

City: Hobbs State: NM Zip: 89402

Phone #: 2-2236 Fax #: 2-6949

Project #: KT0 Project Owner: KT0

Project Name: XT0 ENSU B 904 Aachen

Project Location: Manurem

Sampler Name: _____

FOR LAB USE ONLY

Lab I.D. _____ Sample I.D. _____

Matrix: GRAB OR (C)IMP

Matrix: GROUNDWATER

Matrix: WASTEWATER

Matrix: SOIL

Matrix: CRUDE OIL

Matrix: SLUDGE

Matrix: OTHER:

Matrix: ACID/BASE:

Matrix: ICE / COOL

Matrix: OTHER:

Matrix: _____

P.O. #: _____

Company: _____

Address: _____

City: _____

State: _____ Zip: _____

Phone #: _____

Fax #: _____

DATE _____

TIME _____

Phone Result: Yes No

Fax Result: Yes No

Additional Phone #: _____

Additional Fax #: _____

REMARKS: _____

Delivered By: (Circle One) _____

Sampler - UPS - Bus - Other: _____

Received By: (Lab Staff) _____

Checked By: (Initials) _____

† Cardinal cannot accept verbal changes. Please fax written changes to 505-393-2476.



ARDINAL LABORATORIES

PHONE (526) 673-700 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
EDDIE SEAY CONSULTING
ATTN: EDDIE SEAY
601 W. ILLINOIS
HOBBS, NM 88242
FAX TO: (505) 392-6949

Receiving Date: 12/20/06
Reporting Date: 12/29/06
Project Owner: XTO
Project Name: XTO ENSU B 906 HEADER
Project Location: MONUMENT, NM

Sampling Date: 12/20/06
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: NF
Analyzed By: BC

LAB NUMBER	SAMPLE ID	GRO (C ₈ -C ₁₀) (mg/Kg)	DRO (>C ₁₀ -C ₂₈) (mg/Kg)
ANALYSIS DATE:		12/28/06	12/28/06
H11926-1	906-1 B	<10.0	<10.0
H11926-2	906-2 W	<10.0	<10.0
H11926-3	906-3 S	<10.0	<10.0
H11926-4	906-4 N	<10.0	<10.0
H11926-5	906-5 E	<10.0	<10.0
Quality Control		780	811
True Value QC		800	800
% Recovery		97.5	101
Relative Percent Difference		2.6	1.6

METHOD: SW-846 8015 M

* PID less than 10 ppm

Burgess A. Cook
Chemist

12/29/06
Date

H11926

PLEASE NOTE: Liability and Damages: Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analysis. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.