

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company <i>Eagle Disposal</i>	Contact <i>Scott Curtis</i>
Address <i>1212 El Caminito</i>	Telephone No. <i>392-9134</i>
Facility Name <i>F-29</i>	Facility Type <i>SWD</i>
Surface Owner <i>Eagle Disposal</i>	Mineral Owner <i>OXY</i>
Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>F</i>	<i>29</i>	<i>18S</i>	<i>38E</i>	<i>1880'</i>	<i>North</i>	<i>1745'</i>	<i>West</i>	<i>Lca</i>

Latitude _____ Longitude _____

NATURE OF RELEASE


Type of Release <i>Produced water</i>	Volume of Release <i>60-80</i>	Volume Recovered <i>60</i>
Source of Release <i>Load Line</i>	Date and Hour of Occurrence	Date and Hour of Discovery <i>11-11-06 9:30 AM</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>11-11-06 9:00 AM</i> <i>Gary Wink - Chris Williams</i>	<i>9:30 AM</i>
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	<i>N/A</i>

If a Watercourse was Impacted, Describe Fully.* *N/A*

Describe Cause of Problem and Remedial Action Taken.* *Broken Connection in Load Line
changed entire Load Line to poly.*

Describe Area Affected and Cleanup Action Taken.*
*APPROX: 20' x 100' = 2000' on side - South of Location
Had VACUUM TRUCK & BACKHOE ON LOCATION BY 9:00 AM 11-11-06. PICK UP WATER
& DIG UP CONTAMINATED DIRT.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: <i>Scott Curtis</i>	Approved by District Supervisor: <i>Chris Williams</i>	
Title: <i>Partner</i>	Approval Date: <i>11/17/07</i>	Expiration Date:
E-mail Address: <i>UPC@Valornet.com</i>	Conditions of Approval: <i>Discovered</i>	Attached <input type="checkbox"/>
Date: <i>11-22-06</i> Phone: <i>631-0628</i>	<i>11/11/06</i>	

* Attach Additional Sheets If Necessary

RP# 1131

Eagle Disposal
F-29
12-12-06

N ↑

W. CO. Rd.

Load Line
Buried

Unloading
Station

Leak
site

X well

#4

C-Channel Fence

Barbed-wire Fence

Low spot

#3

#1

#2

Dug out
Approx 1'

20'x100'

X Dead man
marker



11-11-06

Spill Reported @ 8:30 AM.

Vacuum truck & Backhoe on Location @ 8:45-9:00

Picked up approx 60 bbls water @ low spot

Dug out 6" x 8" inches of stock pile on Location for Disposal

12-12-06

Dug out another 6" @ low spot

take four samples to Lab

Samples 1, 2, 3 were taken @ 1' depth.

Sample 4 @ surface

REQUIRED:

- 1) HORIZ & VERTICAL DELINEATION VIA SAMPLING TO 100PPM TPH, 250 CHLORIDE
- 2) CHLORIDE OF WATER SPILLED
- 3) STATUS OF "DUG UP CONTAMINATED DIET"
- 4) SUBMIT AS 'WORK PLAN' ASAP

per Larry Johnson



PHONE (325) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
 EAGLE DISPOSAL
 ATTN: SCOTT
 1212 EL CAMINITO
 HOBBS, NM 88240
 FAX TO:

Receiving Date: 12/12/06
 Reporting Date: 12/15/06
 Project Number: F-29
 Project Name: NOT GIVEN
 Project Location: W.CO.RD.

Sampling Date: 12/12/06
 Sample Type: SOIL
 Sample Condition: COOL & INTACT
 Sample Received By: HM
 Analyzed By: BC/AB

LAB NUMBER	SAMPLE ID	TPH (mg/Kg)	CI* (mg/Kg)
ANALYSIS DATE:		12/14/06	12/13/06
H11890-1	#1	<10	208
H11890-2	#2	<10	304
H11890-3	#3	<10	112
H11890-4	#4	<10	416
Quality Control		233	490
True Value QC		240	500
% Recovery		97.2	98.0
Relative Percent Difference		1.8	0.0

METHODS: TPH-EPA 600/4-79-020 418.1; CI-Std. Methods 4500-CI'B

*Analyses performed on 1:4 w:v aqueous extracts.

Bryant A. Ashe
 Chemist

12/15/06
 Date

H11890

PLEASE NOTE: Liability and Damages Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.