

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RP# 1186

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**  Initial Report  Final Report

Name of Company DKD, L.L.C.	Contact Danny R. Watson
Address Box 682 Tatum, NM 88267	Telephone No.(cell) 505-369-5024 (office) 505-398-3490
Facility Name Vulture	Facility Type SWD

Surface Owner State	Mineral Owner State	Lease No.1 (PC# 27312)
---------------------	---------------------	------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	14	15S	33E	330	North	330	West	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release salt water	Volume of Release 120	Volume Recovered 118
Source of Release Pressure gauge failure	Date and Hour of Occurrence 1/12/07 3 AM	Date and Hour of Discovery 1/12/07 5:30AM
Was Immediate Notice Given? Required <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Hobbs OCD Gary Wink	
By Whom? Danny R. Watson	Date and Hour 1/12/07 7:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. None	

If a Watercourse was Impacted, Describe Fully.\* None

Describe Cause of Problem and Remedial Action Taken.\*  
Pressure gauge failure, water released on ground but inside location. No water outside location. Vacuum truck on location within 2 hours & picked up water. Took backhoe & dug out mud est. 4" to 8". Stacked up and ready to haul to land farm.

Describe Area Affected and Cleanup Action Taken.\*  
When weather breaks will haul off muddy soil. As of now freezing rain & snow is here 1/15/07. Will check with OCD Environmental people for further instructions.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Danny R. Watson</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Danny R. Watson	Approved by District Supervisor: <i>Chris Williams</i>	
Title: Owner DKD	Approval Date: 1/23/07	Expiration Date: 2/23/07
E-mail Address:	Conditions of Approval: <i>Will haul contaminated soil to landfill.</i>	Attached <input type="checkbox"/>
Date: 1/15/07	Phone: 398-3490	

\* Attach Additional Sheets If Necessary  
*facility - APAC 0703037187 incident - nPAC 0703037277 application - nPAC 0703037458*