

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Samson Resources Company	Contact: Autumn Long
Address: Two West Second Street, Tulsa, OK 74103	Telephone No.: (918) 591-1791
Facility Name: P.Q. Osudo State Com No. 002	Facility Type: Producing Gas Well

Surface Owner: State	Mineral Owner: Samson Resources Co.	Lease No.:
----------------------	-------------------------------------	------------

LOCATION OF RELEASE

API# 3025363490000

Unit Letter P	Section 16	Township 21S	Range 35E	Feet from the 760	North/South Line South	Feet from the 660	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude: 32.47359 Longitude: -103.36555

NATURE OF RELEASE

Type of Release: Condensate & Produced Water	Volume of Release: 24 Barrels	Volume Recovered: 6 Barrels
Source of Release: Equipment Failure - Recycle Valve Froze and Burst	Date and Hour of Occurrence: 1/15/07 at approx. 11:00 a.m.	Date and Hour of Discovery: 1/15/07 11:00 a.m.
Was Immediate Notice Given? Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Verbal Notification given to Gary Wink	
By Whom? : Autumn Long	Date and Hour: 1/17/07 at 9:10 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

The recycle valve froze and burst causing the release of 12 barrels condensate and 12 barrels produced water. Well was immediately shut-in, emptied tank to loading/hauling tank truck and vacuumed-up standing fluids; affected area dug up and fertilized.

Describe Area Affected and Cleanup Action Taken.*

Release was contained within firewall; standing fluids vacuumed-up; affected area was dug up and fertilized.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Autumn M. Long</i>	Approved by District Supervisor: <i>[Signature]</i>	
Printed Name: Autumn Long	Approval Date: 2-2-07	Expiration Date:
Title: Associate Environmental Specialist	Conditions of Approval:	Attached <input type="checkbox"/>
E-mail Address: Along@samson.com		
Date: January 17, 2007 Phone: (918) 591-1364		

* Attach Additional Sheets If Necessary

Incident - NPAC 0703632943
application - pPAC 0703633058

RP# 1189



Samson Plaza
Two West Second Street
Tulsa, Oklahoma 74103-3103
USA
918/591-1791
Fax 918/591-1796

SENT VIA CERTIFIED MAIL

January 17, 2007

State of New Mexico Energy Minerals and Natural Resources
District 1
Attn: Gary Wink
1625 N. French Drive
Hobbs, NM 88240

Reference: Release Notification and Corrective Action
Operator: Samson Resources Company
Location: P.Q. Osudo State Com No. 002
Section 16, T21S-R35E
Lea County, NM

Dear Mr. Wink:

Per the telephone notification to you today, at approximately 9:10 a.m., please find attached a completed Form C-141 regarding the release and remedial action taken at the above referenced location.

Please recognize it is Samson's intent to operate in an environmentally responsible manner and to maintain compliance with applicable laws and regulations. I trust this information will satisfy any concerns the State of New Mexico Energy Minerals and Natural Resources may have regarding this incident. If you need additional information, please feel free to contact me at (918) 591-1364.

Thank you.

Sincerely,

Samson Resources Company

A handwritten signature in cursive script that reads 'Autumn M. Long'.

Autumn Long
Associate Environmental Specialist

DB:492
Attachment

cc: Gerry Petree - Superintendent