

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Cimarex of Colorado	Contact	Hugo NAEGELE JR
Address	300 TEXAS P.O. BOX 1237, EUNICE, NM	Telephone No.	505-390-9394
Facility Name	JW Cooper #7	Facility Type	Oil & Gas facility

Surface Owner	Randy Crawford RRR RANCH	Mineral Owner		Lease No.	
---------------	-----------------------------	---------------	--	-----------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	14	24S	36E		NW		SE	LEA

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produce Water	Volume of Release	78 bbls	Volume Recovered	78 bbls
Source of Release	WATER TANK RAN OVER	Date and Hour of Occurrence	3/16/07	Date and Hour of Discovery	4am 3/16/07
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	GARY WINK NMOCD (via voice mail) + LARRY JOHNSON (via voice mail)		
By Whom?	Hugo NAEGELE JR	Date and Hour	3/16/07 9:53am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Power failure due to the storm that went by. Called pumper to check out alarm. Pumper found water tank running over. Power on transfer pump was out, but power to the PC Pump was still on. Called trucking company for vacuum truck to pick up spill & haul wtr. The pumper built up the dike to keep the water in the dike.

Describe Area Affected and Cleanup Action Taken.* The area affected was on the lease road & well location. Didn't notice any damage to pasture. Called for a vacuum truck to pick up spill & haul water. Had gang & backhoe clean up around tanks & build up firewall. It was hard to find any damage to the well location & road due to the heavy rain that day.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>HNAEGL</i>	OIL CONSERVATION DIVISION	
Printed Name:	Hugo NAEGELE JR	Approved by District Supervisor:	<i>[Signature]</i>
Title:	Production Foreman	Approval Date:	3.19.07
E-mail Address:	hnaegele@cimarex.com	Expiration Date:	3/19/07
Date:	3-16-07	Phone:	505 390-9394
		Conditions of Approval:	Attached <input type="checkbox"/>
		1) CHLORIDE CONTENT OF SPILLED WTR IS TO ALWAYS BE INCLUDED	

* Attach Additional Sheets If Necessary
ON C-141
incident - n PAC 0707849032
application - n PAC 0707849129
2) THIS WILL BE POSTED AS FINAL REPORT
IRP # 1241