

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact Jesse A. Sosa
Address 3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5	Telephone No. (505)391-3126
Facility Name Warren Unit Blinbry Tubb WF # 80	Facility Type Water Injection Well

Surface Owner Fee Land	Mineral Owner BLM	Lease No. LC031695B
------------------------	-------------------	---------------------

LOCATION OF RELEASE

API # 3002 S 26642 0000


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	33	20S	38E	1980	North	1980	East	Lea

50'

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 266 bbls	Volume Recovered 220 bbls
Source of Release 2" steel line	Date and Hour of Occurrence 1/20/07 10:41 am	Hour of Discovery 1/20/07 1p
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Jesse Sosa	Date and Hour 01/22/07 10:41 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A buried 2" steel injection line leaked possibly due to corrosion, cause can not be determined until such time as the line can be dug out and inspected/repared. The line is temporarily shut in waiting for the New Mexico One Call to clear for excavation.

Describe Area Affected and Cleanup Action Taken.*

Affected area of 39' X 107' was on pasture land. A vacuum truck was used to pick up free liquids (220 bbls of produced water was recovered). The site will be delineated to determine what further clean up will be needed. Chlorides - 50,000 ppm.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jesse A. Sosa</i>	OIL CONSERVATION DIVISION	
Printed Name: Jesse A. Sosa	Approved by District Supervisor: <i>J. Johnson</i>	
Title: HSER Lead	Approval Date: 3.19.07	Expiration Date: 6.19.07
E-mail Address: Jesse.A.Sosa@conocophillips.com	Conditions of Approval: SUBMIT DELINEATION RESULTS TO OCD w/ REMEDIATION PLAN FOR APPROVAL	Attached <input type="checkbox"/>
Date: 01/25/2007	Phone: (505)391-3126	

* Attach Additional Sheets If Necessary

incident - n PAC 0707849284
application - p PAC 0707849384

RP# 1229