

DATE RECD?

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

Initial Report     Final Report

Name of Company	CHESAPEAKE OPERATING, INC.	Contact	BRADLEY BLEVINS
Address	P. O. BOX 190 HOBBS, NM 88241	Telephone No.	505-391-1462
Facility Name	Trinity Burrus Abo Unit #26	Facility Type	Producing Well <b>API</b>

Surface Owner	Burrus	Mineral Owner		Lease No.	
---------------	--------	---------------	--	-----------	--

**API # 30025359850000**

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>B</b>	<b>27</b>	12S	38E					LEA

**~36'**

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

#### NATURE OF RELEASE

Type of Release	PRODUCED WATER	Volume of Release	160 BBLs	Volume Recovered	30 BBLs
Source of Release	WATER PUMP FAILURE	Date and Hour of Occurrence	1/18/07 7:00 P.M.	Date and Hour of Discovery	1/19/07 9:00 A.M.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	BRADLEY BLEVINS	PAT CAPERTON			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour 1/19/07 10:00 A.M.			
If YES, Volume Impacting the Watercourse.					

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
WATER PUM FAILURE RELEASING 160 BBLs OF PRODUCED WATER TO LOCATION SURFACE. VACCUM TRUCKS DISPATCHED TO RECOVER AS MUCH FLUID AS POSSIBLE.  
**NEED CHEMICAL OF NTR SPILLED ON INITIAL REPORT**

Describe Area Affected and Cleanup Action Taken.\*  
30 BBLs OF PRODUCED WATER WAS RECOVERED. SOIL REMEDIATION ACTIVITIES COMMENCED. SOIL WILL BE EXCAVATED, SAMPLED, AND BACKFILLED UPON APPROVAL FROM NMOCD.  
**NEED AREAL DIMENSIONS OF SPILL**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Cliff P. Brunson</i> for Chesapeake Operating, Inc.		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: CLIFF P. BRUNSON	Approved by District Supervisor: <i>[Signature]</i>		
Title: PRESIDENT	Approval Date: 3-19-07	Expiration Date: 6-19-07	
E-mail Address: CBRUNSON@BBCINTERNATIONAL.COM	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 2/23/07      Phone: 505-397-6388	<b>NEED FULL HORIZ &amp;</b>		

\* Attach Additional Sheets If Necessary

incident - nPACO707924170  
application - nPACO707924248

VERTICAL SAMPLE REPORT  
- NOTIFY PRIOR TO  
BACKFILL FOR INSPECTION  
AS THIS IS SENSITIVE AREA -  
RPT# 1217