

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Chevron Midcontinent LP	Contact	Larry Ridenour
Address	HCR 60 Box 423 Lovington, NM 88260	Telephone No.	505-396-4414 x102
Facility Name	Lovington San Andres Unit #24	Facility Type	Injection well
Surface Owner	City of Lovington	Mineral Owner	State
		Lease No.	B7845

LOCATION OF RELEASE

API

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	36	16S	36E	660	South	660	East	Lea

AP# 30025 037810000 Latitude_N 32 deg 52 min 23.6 sec Longitude_W 103 deg 18 min 5.3 sec

NATURE OF RELEASE

Type of Release	produced water	Volume of Release	200 bbls	Volume Recovered	30 bbls
Source of Release	injection line	Date and Hour of Occurrence	12/14/07 3:45 AM	Date and Hour of Discovery	12/14/07 7:45 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Pat Caperton (left message on answering machine)		
By Whom?	Larry Ridenour	Date and Hour	2/14/07 9:15 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Line not excavated yet. Expect root cause will be internal corrosion. Well was shut in and line was isolated.
**NEED CHLORIDE?*

Describe Area Affected and Cleanup Action Taken.*
Affected area approximately 200' x 40'.
**NEED WORK PLAN, SAMPLE TO CLEAN. TO WHERE?*
Affected area was marked with flags. One call will be done and contaminated soil down to rock will be removed. Once the soil has been removed samples will be taken to check for extent of remaining contaminated soil. Contaminated soil will be replaced with fresh soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Larry D Ridenour</i>	OIL CONSERVATION DIVISION	
Printed Name:	Larry D. Ridenour	Approved by District Supervisor:	<i>[Signature]</i>
Title:	Operations Representative	Approval Date:	3-28-07
E-mail Address:	LRidenour@Chevron.com	Expiration Date:	6-28-07
Date:	2/15/07	Conditions of Approval:	<i>*NOTED ABOVE</i>
Phone:	505-396-4414 x102	Attached	<input type="checkbox"/>

* Attach Additional Sheets If Necessary

incident - nPAC0708 824677
application - nPAC0708 824895

FINAL C-141 w/ DOCUMENTS
ON CORRECTION

RPT# 1216