

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report  Final Report

Name of Company	Cimarex Energy Co. of Colorado	Contact	David Hayes
Address	PO Box 1237, Eunice, NM 88231	Telephone No.	505-394-0613
Facility Name	State 21 # 3	Facility Type	Tank battery
Surface Owner	STATE	Mineral Owner	State
		Lease No.	

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	21	16S	37E	1650	North	330	East	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	20	Volume Recovered	0
Source of Release	Water tank	Date and Hour of Occurrence	2-19-07	Date and Hour of Discovery	2-19-07
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Bob Jennings, Cimarex, Dallas, Tx		
By Whom?	Mr. Medina - Rancher	Date and Hour	2-19-07		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

WTR 40'-50'



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* check valve on SWD line leaked allow water to come back into tank and running it over. Tank was emptied and check valve repaired.

\* NEED CHLORIDES OF WTR SPILLED - NEED VERTICAL DECLINATION SUBMITTED

Describe Area Affected and Cleanup Action Taken.\* 72' x 51'. All on battery location. 99% of water evaporated or soaked in. Location was back dragged and fresh caliche put on area.

50 BBL

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>David Hayes</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	David Hayes	Approved by District Supervisor:	<i>[Signature]</i>
Title:	Assistant Production Foreman	Approval Date:	3-28-07
E-mail Address:		Expiration Date:	4-28-07
Date:	2-22-07	Conditions of Approval:	*SEE ABOVE NOTES
Phone:	394-0613	Attached	<input type="checkbox"/>

\* Attach Additional Sheets If Necessary  
 facility - PPACO708825339  
 incident - PPACO708825410  
 application - PPACO708825484

RP# 1270