

To: PAT CAPERTON

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Artec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report

Final Report

Name of Company John H. Hendrix, Corp.	Contact Marvin Burrows (Prod. Supt)
Address PO Box 910	Telephone No. 505-394-2649
Facility Name A.M. Drinkard tank battery.	Facility Type Tank battery.

Surface Owner S&D Ranch (Flap Sims)	Mineral Owner Drinkard	Lease No. 012024
-------------------------------------	------------------------	------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	30	22 S	38 E	2020	S	560	E	Lea

48'

N 32 DEG 21' 41" W 103 DEG 5' 32.6"

NATURE OF RELEASE

Type of Release OIL / WATER	Volume of Release 4 BO 1/2 BW	Volume Recovered 3 BBLs
Source of Release TANK (GUN BARREL)	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? Yes No Not Required NR	If YES, To Whom? CALLED LAND OWNER (FLAP SIMS) AND LEFT MESSAGE TO PAT CAPERTON, OCD HOBBS	
By Whom? MARVIN BURROWS	Date and Hour 9 AM 2/13/07	
Was a Watercourse Reached? Yes No NO	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
EQUALIZER LINE BETWEEN GUN BARREL AND OIL STOCK TANK PLUGGED UP, CAUSING GUN BARREL TO RUN OVER.

Describe Area Affected and Cleanup Action Taken.*
NEARLY ALL FLUID STAYED INSIDE BATTERY FIREWALLS, BUT THERE WAS A STIFF WIND OUT OF THE WEST, WHICH CARRIED A MIST OVER THE BATTERY FENCE ONTO THE PASTURE GRASS.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: MARVIN BURROWS		
h	h	
e environment.		
a	ddition, NMOCD acceptance	r
c	operator of responsibility for complia	t does not relieve
any other federal, state, or local laws and/or regulations. I I I	Sig	

CONDITIONS:
NEED REMEDIATION
PLAN w/ DELINEATION
OF INSIDE BTRY AREA
B. J. BURROWS

RP# 1200

Facility - PPAC0709631687
Incident - nPPAC0709631801
application - pPPAC0709631901

Printed Name: Title: P