

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
**District II**  
1301 W. Grand Avenue, Artesia, NM 88210  
**District III**  
1000 Rio Brazos Road, Aztec, NM 87410  
**District IV**  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: OXY USA WTP, LP	Contact: Rick Kerby
Address: 102 S. Main St., P.O. Box 1988, Carlsbad, NM 88220	Telephone No.: 505-887-8337
Facility Name: Federal AB Lease Battery	Facility Type: Lease Battery
Surface Owner: BLM	Mineral Owner
	Lease No.

**LOCATION OF RELEASE**

Unit Ltr	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	11	18 South	33 East					Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release: <b>Produced Fluids</b>	Volume of Release: <b>17 bbls</b>	Volume Recovered: <b>10 bbls</b>
Source of Release: <b>Water Leg on Heater Treater</b>	Date and Hour of Occurrence: <b>03/27/2007 11:00 AM</b>	Date and Hour of Discovery: <b>03/27/2007 12:00 PM</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Ninty degree "L" on water leg came loose. Fluid was picked up and hauled to disposal.

Describe Area Affected and Cleanup Action Taken.\*  
Fluid spilled on location and ran into pasture. Fluid was picked up and hauled to disposal. Area allowed to dry. Contaminated dirt will be temporarily amassed onto plastic liner on location. Remedial plan will be submitted to NMOCD and BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rick Kerby</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Rick Kerby	Approved by District Supervisor: <i>[Signature]</i>	
Title: HES Specialist <i>636-4972</i>	Approval Date: 4.6.07	Expiration Date: 6.6.07
E-mail Address: rick.kerby@oxy.com	Conditions of Approval: <i>*</i>	Attached <input type="checkbox"/>
Date: 03/27/2007	Phone: 505/887-8337	

\* Attach Additional Sheets If Necessary

facility - PPAC0709933765  
incident - PPAC0709933855 4.6.07 (CAUSE) RICK - HE TO GET  
application - PPAC0709933956 2:30P  
LUMP LETTER & PLAN  
TO ME TO ME FROM

RP# 1272