

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company ConocoPhillips Company	Contact Jesse A. Sosa
Address 3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5	Telephone No. (505)391-3126
Facility Name SEMU Cass Penn	Facility Type Battery

Surface Owner ConocoPhillips	Mineral Owner BLM	Lease No.
-------------------------------------	--------------------------	-----------

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	14	20S	37E	1650	South	2250	West	Lea

Latitude _____ Longitude _____

wtr 70'

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 24	Volume Recovered 20
Source of Release 3" check valve on transfer line	Date and Hour of Occurrence 4/8/07 5:00 am	Hour of Discovery 4/8/07 7am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD-Caperton(voicemail) BLM - BadBear(voicemail)	
By Whom? Jesse Sosa	Date and Hour 4/12/2007 3:50 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
There was an accidental discharge of 24 bbls fluid bbl - wtr from a plug on flapper shaft on a check valve. The check valve was on a 3" transfer line downstream of transfer pump. The spill was not contained in a dike and 20 BBLs fluid was recovered.

Describe Area Affected and Cleanup Action Taken.* *(4500)*
Affected area was 90' X 50' all on caliche pad. MSO called a vacuum truck out and 20 bbls was recovered. No cows were presence. Area will be remediated in accordance with NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jesse A. Sosa</i>	OIL CONSERVATION DIVISION	
Printed Name: Jesse A. Sosa	Approved by District Supervisor: <i>[Signature]</i>	
Title: HSER Lead	Approval Date: 4-25-07	Expiration Date: 6-25-07
E-mail Address: Jesse.A.Sosa@conocophillips.com	Conditions of Approval: SUBMIT CLOSURE C-141	
Date: 04/12/2007 Phone: (505)391-3126	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

w/Documentation By IRP # 1296

*incident - n PACO 7 11542882
application - p PACO 7 11543092*