

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company <b>ConocoPhillips Company</b>	Contact <b>Jesse A. Sosa</b>
Address <b>3300 North A St., Bldg. 6, Midland, TX 79705-5406</b>	Telephone No. <b>505.391.3126</b>
Facility Name <b>Lockhart B28 # 6</b>	Facility Type <b>Oil and Gas</b>

Surface Owner <b>BLM</b>	Mineral Owner <b>BLM</b>	Lease No <b>NM90162</b>
--------------------------	--------------------------	-------------------------

**LOCATION OF RELEASE**


API# 30025 04814 0000

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	28	21S	36E	660	North	660	East	Lea

Latitude Longitude

**NATURE OF RELEASE**

Type of Release <b>Oil And Produced Water</b>	Volume of Release 18bbl (1oil, 17water)	Volume Recovered (0oil, 10water)
Source of Release <b>3" Poly flowline</b>	Date and Hour of Occurrence 11/30/2006 7:00 am	Date and Hour of Discovery 11/30/2006 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>NMOCD-Pat Caperton (voicemail) BLM-Trisha Bad Bear (voicemail)</b>	
By Whom? <b>Jesse Sosa</b>	Date and Hour <b>12/08/2006 3:00 pm</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

**There was an accidental discharge of 1 BO and 17 BPW from a 3" poly flowline due to freezing temperatures during normal operations. The fluid was not contained. There was 10 BPW recovered.**

Describe Area Affected and Cleanup Action Taken.\*

**Affected area of 39' X 69' was on pasture and area of 78' X 39' was on caliche pad. There was no livestock present. Area will be remediated in accordance with NMOCD guidelines.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jesse A. Sosa</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Jesse A. Sosa</b>	Approved by District Supervisor: <i>J. Johnson</i>	
Title: <b>HSER Lead</b>	Approval Date: <b>5.25.07</b>	Expiration Date: <b>8.25.07</b>
E-mail Address: <b>Jesse.A.Sosa@conocophillips.com</b>	Conditions of Approval: Attached <input type="checkbox"/>	
Date: <b>12/08/2006</b>	Phone: <b>505.391.3126</b>	

- Attach Additional Sheets If Necessary

incident - n PAC0714546403  
application - p PAC071456542

n/ DOCUMENTATION

RPT# 1373

SUBMIT FINAL C. 141 24