

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company YATES PETROLEUM CORPORATION	OGRID Number 25575	Contact SHERRY BONHAM
Address 105 S 4 <sup>TH</sup> STREET		Telephone No. 505.748.1471
Facility Name TENNECO SWD BATTERY	API Number 30 025 25762	Facility Type SWD
Surface Owner STATE	Mineral Owner STATE	Lease No. 30-025-25762

**LOCATION OF RELEASE**

Unit Letter P	Section 2	Township 11S	Range 34E	Feet from the 330	North/South Line SOUTH	Feet from the 990	East/West Line EAST	County LEA
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 33.37707 Longitude 103.4772

**NATURE OF RELEASE**

Type of Release PRODUCED WATER AND CRUDE OIL	Volume of Release 150 B/PW AND 10 B/O	Volume Recovered 130 B/PW AND 5 B/O
Source of Release GUN BARREL	Date and Hour of Occurrence 1/07/07 2:00 PM	Date and Hour of Discovery 1/07/07 2:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? PAT CAPERTON	
By Whom? SHERRY BONHAM	Date and Hour 1/08/07 8:55 AM VIA VOICE MAIL AND FOLLOW UP E-MAIL	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* WATER LEG PLUGGED CAUSING GUN BARRREL TO HIGH LEVEL AND RUN OVER. REPAIRED WATER LEG.		
Describe Area Affected and Cleanup Action Taken.* AN APPROXIMATE 100' X 35' AREA IMPACTED WITHIN BERM. AN APPROXIMATE 70' X 230' OUTSIDE BERMED AREA WAS SPRAYED. VACUUM TRUCK AND CREW CALLED IN. ALL STANDING FLUIDS VACUUMED. IMMEDIATELY SCRAPED UP IMPACTED MATERIALS AND DISPOSED AT LAND FARM. SITE EVALUATION IN PROGRESS. WORK PLAN TO FOLLOW. SITE RANKING: <u>20</u>		

Received  
Hobbs  
060

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Sherry Bonham	Approved by District Supervisor:	
Title: Environmental Regulatory Agent	Approval Date: 5.29.07	Expiration Date: 8.29.07
E-mail Address: sherryb@ypcnm.com	Conditions of Approval: SUBMIT FINAL REPORT w/ SUPPORTING DOCUMENTATION	Attached <input checked="" type="checkbox"/>
Date: January 11, 2007	Phone: 505.748.1471	

\* Attach Additional Sheets If Necessary

incident - n PAC0715049384  
application - pPAC0715049491

RP # 1177