

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact Kenneth N. Andersen
Address 3300 North A St., Bldg. 6, Midland, TX 79705-5406	Telephone No. 505.391.3158
Facility Name EVGASU 2175-002	Facility Type Oil and Gas

Surface Owner State of New Mexico	Mineral Owner State of New Mexico	Lease No. API # 30-025-02849
--	--	-------------------------------------

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	28	17S	35E					Lea

Latitude **32.81142N** Longitude **-103.47113W**

WTR 60-70

NATURE OF RELEASE

Type of Release Crude Oil & Produced Water W/Chlorides = 62,000mg/L	Volume of Release 13 bbl (2 oil, 11 water)	Volume Recovered (1 oil, 9 water)
Source of Release EVGSAU 2175-002 flowline ~ 600ft west of EVGSAU 2864-013 (API # 30-025-02916)	Date and Hour of Occurrence 12/03/2006 1500hrs	Date and Hour of Discovery 12/04/2006 1100hrs
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The spill was caused by external corrosion of 2" steel line pipe used for a flowline at a road crossing. A vacuum truck was called and 10 bbls of fluid were recovered.		
Describe Area Affected and Cleanup Action Taken.* 2'X600' of dry black soil/caliche rock road with no cows present. The spill site will be delineated and remediated in accordance with NMOCD guidelines.		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kenneth N. Andersen</i>	OIL CONSERVATION DIVISION	
Printed Name: Kenneth N. Andersen	Approved by District Supervisor: <i>[Signature]</i>	
Title: Environmental Specialist	Approval Date: 5-29-07	Expiration Date: 8-29-07
E-mail Address: ken.n.andersen@conocophillips.com	Conditions of Approval: <input checked="" type="checkbox"/> Attached <input type="checkbox"/>	
Date: 12/08/2006 Phone: 505.391.3158	SUBMIT FINAL C 141 w/ SUPPORTING DOCUMENTATION BY RPH 1394	

• Attach Additional Sheets If Necessary
*incident - pPAC0715049612
application - pPAC0715049691*