

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Targa Midstream Services L P	Contact: James Lingnau 505.394.2534, Chuck Tolsma 505.631.6026
Address: PO Box 1909 Eunice, NM 88231	Telephone No. (505) 394-2534
Facility Name: Eunice Gathering System	Facility Type Gas Processing Plant
Surface Owner: Deck Estate	Mineral Owner:
	Lease No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	5	23S	37E					Lea

Latitude 32.34343000 N Longitude -103.18975500 W

NATURE OF RELEASE



Type of Release: Gas and Produced Liquids	Volume of Release: Less than 500mcf of gas and Approximately 10 bbls. liquid.	Volume Recovered: 5 or 6 barrells
Source of Release: 16" Gas Gathering Pipeline leak	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 2:30PM May 22, 2007
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton OCD	
By Whom? Rebecca Woodell	Date and Hour 2 PM May 23, 2007	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken. *
A 16 inch gathering line 2 feet below the surface with 12 psig and 1 mcf of flow and less than 100 ppm of H2S developed a 1/2 inch hole and released gas and liquids that were lying in the line. Field operators immediately blocked in line. Repairs were made to the line with a clamp and plans made to replace that section of line.

Describe Area Affected and Cleanup Action Taken.*
Targa will replace pipe as needed. The area will be cleaned and tested per OCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
D Printed Name: Don Embrey	Approved by District Supervisor: 	
Title: Advisor	Approval Date: 5.31.07	Expiration Date: 7.31.07
E-mail Address: dembrey@targaresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/29/07 Phone: (432) 688-0546	- Full Horiz & Vertical Delimitation	

* Attach Additional Sheets If Necessary

incident - n PAC 0715 138290
application - p PAC 0715 138145

To 'clean' + 1, ATTACH ALL DOCUMENTATION,
BILLS OF LADEN FOR REMOVED SOILS TO CLOSURE C-141
RPH# 1398