

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company PHOENIX HYDROCARBONS OPERA	Contact CLARENCE CRAIG
Address P O BOX 3638	Telephone No. 505-370-0825
Facility Name NM STATE BB LEASE BATTERY	Facility Type TANK BATTERY

Surface Owner CARL L JOHNSON	Mineral Owner STATE	Lease No. N/A
------------------------------	---------------------	---------------

**LOCATION OF RELEASE**

Unit Letter	Section	TOWNSHI	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	14	10-S	32-E					LEA NEW MEXICO

Latitude 33° 26' 65N Longitude 103° 38' 44W

*LUTR = 50'*

**NATURE OF RELEASE**


Type of Release CRUDE OIL	Volume of Release 25 BBLS	Volume Recovered 18 BBLS
Source of Release TANK OVERFLOWED	Date and Hour of Occurrence 1 PM	Date and Hour of Discovery 8 3/23/07
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? GARY WINK	
By Whom? PHYLLIS R GUNTER	Date and Hour 12:47 PM 3/23/07	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
CIRCULATING PUMP MALFUNCTIONED AND FILED TANK TO OVERFLOWING. 7 BARRELS WERE NOT RECOVERED MOSTLY INSIDE THE BERM. SMALL AREA OUTSIDE THE BERM WILL BE SCRAPED UP AND NEW SOIL BROUGHT IN. AREA INSIDE THE BERM WILL BE REMEDIATED USING PEAT SORB MATERIAL.

Describe Area Affected and Cleanup Action Taken.\*  
AFFECTED AREA IS GRASSY (40' X 50') OUTSIDE TANK BATTERY - OIL SPRAY/MIST DUE TO WINDY CONDITIONS WHEN THE TANK OVERFLOWED. THIS AREA WILL BE TREATED WITH SOAPY FRESH WATER.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.



Signature: <i>Phyllis R Gunter</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: PHYLLIS R GUNTER	Approved by District Supervisor: <i>Carl L Johnson</i>	
Title: AGENT	Approval Date: 6.5.07	Expiration Date: 8.5.07
E-mail Address: PRGUNTER@AOL.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/23/07 Phone: 432-686-9869	SUBMIT FINAL C-141 BY	

\* Attach Additional Sheets If Necessary

*RP# 137  
1419*