

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised March 17, 1999

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Apache Corporation	Contact Mike Warren
Address PO Box 1849 1.5 miles North of Eunice Eunice, New Mexico 88231	Telephone No. 505.394.2743
Facility Name NEDU 704 9-18-03	Facility Type Water injection system 2" fiberglass line

Surface Owner: Millard Deck Estate; representative is L.V. "Flap" Sims II	Mineral Owner	Lease No.
--	---------------	-----------

AP# 30025 099170000

LOCATION OF RELEASE

Unit Letter 15	Section 15	Township T21S	Range R37E	Feet from the	North/South Line	Feet from the	East/West Line	County: Lea Lat. 32° 28' 28.3"N Lon. 103° 09' 10.4"W
-------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	--

NATURE OF RELEASE


Type of Release Produced Water	Volume of Release 500 bbls barrels	Volume Recovered 0.0 bbls barrels
Source of Release Water injection system 2" fiberglass line	Date and Hour of Occurrence 9-18-03 @ 3:00 AM	Date and Hour of Discovery 9-18-03 @ 8:20 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Paul Sheeley and Sylvia Dickie	
By Whom? Pat McCasland, EPI	Date and Hour 9-18-03 @ 9:10 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*
The 2" fiberglass injection line failed for unknown reasons and is being investigated.

Describe Area Affected and Cleanup Action Taken.*
The site will be delineated and remediated in accordance with the NMOCD guidelines. Remedial Goals: TPH 8015m = 1000 mg/Kg, Benzene = 10 mg/Kg, and BTEX, i.e., the mass sum of Benzene, Ethyl Benzene, Toluene, and Xylenes = 50 mg/Kg. A site specific chloride residual will be determined utilizing risk assessment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Mike Warren e-mail - mike.warren@apachecorp.com	Approved by District Supervisor: <i>ENJOY ENER</i> 	
Title: Area Supervisor	Approval Date: 6-5-07	Expiration Date: 8-5-07
Date: September 19, 2003 Phone: 505.394.2743	Conditions of Approval: <input checked="" type="checkbox"/> Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

FINAL REPORT FILE BY

RP# 1214