


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company <b>ConocoPhillips Company</b>	Contact <b>Mickey D. Garner</b>
Address <b>3300 North A St. Bldg 6, Midland, TX 79705-5406</b>	Telephone No. <b>505.391.3158</b>
Facility Name <b>Vacuum Abo Unit 13-3</b>	Facility Type <b>Oil and Gas</b>
Surface Owner <b>State of New Mexico</b>	Mineral Owner <b>State of New Mexico</b>
Lease No <b>30-025-03045-00-00</b>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>C</b>	<b>4</b>	<b>18S</b>	<b>35E</b>					<b>Lea</b>

Latitude **N 32.78050** Longitude **W 103.46401**

**NATURE OF RELEASE**

Type of Release <b>Crude Oil and Produced Water</b>	Volume of Release <b>40bbbl (7oil, 33water)</b>	Volume Recovered <b>(2oil, 10water)</b>
Source of Release <b>2 7/8 Steel Flowline</b>	Date and Hour of Occurrence <b>5-31-2007 07:00</b>	Date and Hour of Discovery <b>6-1-2007 10:30</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Pat Caperton</b>	
By Whom? <b>Bradley Boroughs</b>	Date and Hour <b>6-4-2007 13:05</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>N/A</b>	

If a Watercourse was Impacted, Describe Fully.\*  
**N/A**

*ENLARGE 61,000*

Describe Cause of Problem and Remedial Action Taken.\*

**The leak resulted from external corrosion to a 2 7/8 steel flowline. The MSO shut in the well and called a vacuum truck to pick up free liquids**

Describe Area Affected and Cleanup Action Taken.\*

**A 135' X 75' area of pasture was affected. No cows were present. The spill site will be delineated and remediated in accordance with NMOCD guidelines.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Mickey D. Garner</b>	Approved by District Supervisor:	
Title: <b>HSER Lead</b>	Approval Date: <b>6-11-07</b>	Expiration Date: <b>8-11-07</b>
E-mail Address: <b>Mickey.D.Garner@conocophillips.com</b>	Conditions of Approval: <b>SUBMITTAL OF FINAL C-141</b>	Attached <input type="checkbox"/>
Date: <b>6-5-2007</b> Phone: <b>505.391.3158</b>		

• Attach Additional Sheets If Necessary

*N/SUPPORTING DOCUMENTATION 54*

*RP# 1309  
1409*