

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

X Initial Report ~~X Final Report~~

Name of Company	Chevron Midcontinent LP	Contact	Larry Ridenour
Address	HCR 60 Box 423 Lovington, NM 88260	Telephone No.	505-396-4414 x128
Facility Name	Lovington San Andres Unit #22	Facility Type	oil well

Surface Owner	City of Lovington	Mineral Owner	State	Lease No.	B7845
---------------	-------------------	---------------	-------	-----------	-------

**LOCATION OF RELEASE**


API #30025053510000

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	31	16S	37E	660	South	660	East	Lea

Latitude N 32 deg 52 min 23.6 sec Longitude W 103 deg 18 min 5.3 sec

**NATURE OF RELEASE**

Type of Release	produced water and crude oil	Volume of Release	35 bbl water and 1/2 bbl oil	Volume Recovered	20 bbl fluid
Source of Release	Well head	Date and Hour of Occurrence	06/04/07 10:00 AM	Date and Hour of Discovery	06/04/07 10:00 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Pat Caperton (left message on answering machine)		
By Whom?	Larry Williams	Date and Hour	6/04/07 1:30 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Well was in the process of getting well ready for plugging rig. Tubing was out of the well and well secured for the weekend. Off side casing developed a leak in the nipple between wellhead and casing valve. The entire spill remained on location. Request to do clean up after the well is plugged and abandoned. We will have to do the final clean up of the location since the location is being abandoned.  
Chlorides 35,302 ppm Crude oil gravity 38

Describe Area Affected and Cleanup Action Taken.\*

Affected area approximately 100' x 40'.

Once the well is plugged and abandoned; we will go in and clean up the entire locations. Remove contaminated soil and take to land farm or fill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Larry Williams</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Larry Williams	Approved by District Supervisor: <i>Ennie Lopez</i>	
Title: HES Specialist	Approval Date: 6-29-07	Expiration Date: 9-10-07
E-mail Address: lcwl@Chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/04/07 Phone: 505-396-4414 x128	SUBMIT FINAL C-141	

\* Attach Additional Sheets If Necessary

\* NOTIFY OGD WHEN CLEAN UP COMMENCES

RP#1477