

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**  Initial Report  Final Report

Name of Company	Plantation Operating, LLC	Contact	John Allred
Address	2203 Timberloch Place, Suite 229 The Woodlands, TX 77380	Telephone No.	281-296-7222
Facility Name	C.T. Bates #4 API #30-025-34404	Facility Type	120 BBL Test Tank
Surface Owner	Johnny Chapman	Mineral Owner	Plantation Operating, LLC
		Lease No.	13411

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	10	26S	37E	660'	South	2145'	West	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

*WTR 7100*

Type of Release	Water	Volume of Release	30 BBLs	Volume Recovered	20 BBLs
Source of Release	Lightning	Date and Hour of Occurrence	7/6/07 - 12:00 p.m.	Date and Hour of Discovery	7/7/07 - 8:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Gary Wink		
By Whom?	John Allred	Date and Hour	7/9/07 - 11:20 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

Lightning hit fiberglass water tank 7/6/07 on Friday night. Called White Buffalo Environmental Services for proper clean up.

*Chloride of Water?*

Describe Area Affected and Cleanup Action Taken.\*

Area affected - 100 square feet off pad in pasture. Digging out contaminated dirt and hauling to landfill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	John Allred	Approved by District Supervisor:	
Title:	Engineer	Approval Date:	7.9.07
		Expiration Date:	9.10.07
E-mail Address:	jallred@plantationpetro.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	7/9/07	Phone:	281-296-7222

**SUBMITTAL OF FINAL C-141 BY**  
*W/ ATTACHED DOCUMENTATION*

*RP#1482*

\* Attach Additional Sheets If Necessary