

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	<b>COG Operating LLC</b>	Contact	<b>Diane Kuykendall</b>
Address	<b>550 W. Texas Ave, Ste 1300 Midland, TX 79701</b>	Telephone No.	<b>432-685-4372</b>
Facility Name	<b>Jalpat Yates Unit Battery</b>	Facility Type	<b>Oil Battery</b>
Surface Owner	Mineral Owner	Lease No. <b>301048</b>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>A</b>	<b>13</b>	<b>25S</b>	<b>36E</b>	<b>1050</b>	<b>North</b>	<b>1100</b>	<b>East</b>	<b>Lea</b>

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	<b>produced oil &amp; water leak</b>	Volume of Release	<b>50 BO &amp; 300 BW</b>	Volume Recovered	<b>20 BO &amp; 270 BW</b>
Source of Release	<b>Oil Tank</b>	Date and Hour of Occurrence	<b>7/06/07 time unknown</b>	Date and Hour of Discovery	<b>7/06/07 apprx 11:00 am</b>
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Hobbs NMOCD</b>			
By Whom?	<b>COG Pumper Warren Hunt</b>	Date and Hour	<b>11:00 am 7/06/07</b>		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
**Free water knock off failed sending water to the oil tanks. The oil tank over flowed. Called vacuum truck**

Describe Area Affected and Cleanup Action Taken.\*  
**Leak was contained within the battery. Remediation began 7-6-07 with vacuum truck. Vacuum truck picked up 20 BO & 270 BW. Dig up contaminated dirt & stored at facility. Will have Highland Environmental access and turn in a work plan,**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Diane Kuykendall</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Diane Kuykendall	Approved by District Supervisor: <i>[Signature]</i>	
Title: Regulatory Analyst	Approval Date: <b>7.11.07</b>	Expiration Date: <b>8.20.07</b>
E-mail Address: <a href="mailto:dkuykendall@conchoresources.com">dkuykendall@conchoresources.com</a>	Conditions of Approval: Attached <input type="checkbox"/>	
Date: 7/06/07 Phone: 432-685-4372	- <b>SUBMIT CLEANUP PLAN OF OCD APPROVAL BY</b>	

\* Attach Additional Sheets If Necessary

- **SUBMIT CHLORIDES ON ALL PRODUCED WATER SPILLS ON ORIG C-141**

*RP#1402*

