

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

**OPERATOR**  Initial Report  Final Report

<b>Name of Company:</b> Duke Energy Field Services	<b>Contact:</b> Lynn Ward
<b>Address:</b> 10 Desta Drive, Suite 400-W	<b>Telephone No.:</b> (432) 620-4207
<b>Facility Name:</b> C-23-10 Line - Leak #10	<b>Facility Type:</b> Natural Gas Pipeline

<b>Surface Owner:</b> Aline Sims	<b>Mineral Owner:</b>	<b>Lease No.:</b>
----------------------------------	-----------------------	-------------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	14	20S	35E					Lea

**Latitude:** N 32° 34' 39.03" **Longitude:** W 103° 25' 31.23"

#### NATURE OF RELEASE

<b>Type of Release:</b> Natural Gas	<b>Volume of Release:</b> unknown	<b>Volume Recovered:</b> none
<b>Source of Release:</b> Pipeline	<b>Date and Hour of Occurrence:</b> unknown	<b>Date and Hour of Discovery:</b> January 13, 2006
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> Larry Johnson, NMOCD	
<b>By Whom?</b> Lynn Ward	<b>Date and Hour:</b> January 13, 2006 @ 11:59 A.M.	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse:</b> Not Applicable	

**If a Watercourse was Impacted, Describe Fully.\*** Not Applicable

**Describe Cause of Problem and Remedial Action Taken.\*** An unknown amount of natural gas was released as the result of the structural integrity of the natural gas line failing when the pressure was increased on the line, with no amount recovered from the site. The line was shut in and is scheduled to be replaced.

**Describe Area Affected and Cleanup Action Taken.\*** Approximately 1,600 square-feet of surface area was impacted by the release. Remediation of the site will be in accordance with NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<b>Signature:</b>	<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Lynn Ward	<b>Approved by District Supervisor:</b>	
<b>Title:</b> Environmental Specialist-Western Division	<b>Approval Date:</b> 7.17.07	<b>Expiration Date:</b>
<b>E-mail Address:</b> lcward@duke-energy.com	<b>Conditions of Approval:</b>	<b>Attached</b> <input type="checkbox"/>
<b>Date:</b> 2/2/06 <b>Phone:</b> (432) 620-4207		

\* Attach Additional Sheets If Necessary

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report

Final Report

<b>Name of Company:</b> DCP Midstream, LLC	<b>Contact:</b> Steve Weathers
<b>Address:</b> 370 17 <sup>th</sup> Street, Suite 2500 Denver, CO 80202	<b>Telephone No.:</b> (303) 605-1718
<b>Facility Name:</b> C-23-10 Line – Site #10	<b>Facility Type:</b> Natural Gas Pipeline

<b>Surface Owner:</b> Aline Sims	<b>Mineral Owner:</b> State of New Mexico	<b>Lease No.:</b> 1RP# 422
----------------------------------	---	----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	14	20S	35E					Lea

**Latitude:** N 32° 34' 39.03" **Longitude:** W 103° 25' 31.23"

**NATURE OF RELEASE**



<b>Type of Release:</b> Natural Gas and Natural Gas Liquids	<b>Volume of Release:</b> >5 bbls	<b>Volume Recovered:</b> none
<b>Source of Release:</b> Steel natural gas pipeline	<b>Date and Hour of Occurrence:</b> historical	<b>Date and Hour of Discovery:</b> January 13, 2006
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> Larry Johnson, NMOCD	
<b>By Whom?</b> Lynn Ward, DCP Midstream, LLC	<b>Date and Hour:</b> January 13, 2006 @ 11:59 A.M.	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse:</b> Not Applicable	

**If a Watercourse was Impacted, Describe Fully.\*** Not Applicable

**Describe Cause of Problem and Remedial Action Taken.\*** An unknown amount of natural gas was released as the result of the structural integrity of the natural gas line failing when the pressure was increased on the line. No volume was recovered from the site. The line was shut in and later replaced.

**Describe Area Affected and Cleanup Action Taken.\*** Approximately 1,600 ft<sup>2</sup> of surface area were impacted by the release. Remediation of the site was in accordance with NMOCD guidelines. Approximately 2,180 yd<sup>3</sup> of NGL impacted soil was removed from an excavation of approximately 3,560 ft<sup>2</sup> to a maximum depth of 23-feet bgs. Approximately 800 of the most impacted soil was transported to South Monument Landfarm for treatment. The remaining portion of impacted soil was shredded/aerated on site. Upon receipt of laboratory analytical results indicating remedial thresholds had been achieved, site was backfilled with remediated native soil, clean caliche and topsoil obtained from the landowner. Site remedial thresholds: TPH – 1,000 mg/Kg, benzene – 10 mg/Kg; BTEX – 50 mg/Kg

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<b>Signature:</b> 	<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Steve Weathers	<b>Approved by District Supervisor:</b> 	
<b>Title:</b> Senior Environmental Specialist	<b>Approval Date:</b> 7.17.07	<b>Expiration Date:</b> _____
<b>E-mail Address:</b> swwathers@dcpmidstream.com	<b>Conditions of Approval:</b> _____	<b>Attached</b> <input type="checkbox"/>
<b>Date:</b> 6/29/07 <b>Phone:</b> (303) 605-1710		

\* Attach Additional Sheets If Necessary

Full Closure Report  
scanned under RP#413

RP# 422