

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report

Final Report

Name of Company Chevron USA	Contact TEJAY SIMPSON
Address HCR 60 Box 423 Lovington, N.M. 88260	Telephone No. 505-396-4414 X 101
Facility Name CENTRAL VACUUM UNIT 146	Facility Type INJECTION WELL

Surface Owner Giles Lee	Mineral Owner State of NM	Lease No. 857943
-------------------------	---------------------------	------------------

**LOCATION OF RELEASE**



Unit Letter	Section	Township	Range	Feet from the	South Line	Feet from the	West Line	County
G	31	17.0S	35E	2465 FNL		1335 FEL		Lea

290'

Latitude 32.7920373048 Longitude -103.492826251

**NATURE OF RELEASE - API #30-025-26790**

Type of Release Produced Water	Volume of Release 70-BBLS PRODUCED WATER	Volume Recovered 50 BBLS PW fluids.
Source of Release INJECTION WELLHEAD PSV	Date and Hour of Occurrence 07/22/07	Date and Hour of Discovery 07/22/07 1:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? PATRICIA GILBERT VOICE MAIL	
By Whom? TEJAY SIMPSON	Date and Hour 7/24/2007 8:40 A.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
WATER INJECTION WELL - 1/2" PRESSURE RELIEF VALVE LOCATED ON TOP OF THE SWAB VALVE FAILED AND RESULTED IN A RELEASE OF AN ESTIMATED 70 BARRELS OF PRODUCED WATER. LEAK WAS ISOLATED AND VACUUM TRUCKS DISPATCHED TO THE SCENE. RECOVERED OF 50 BARRELS OF FLUID. RELEASED WATER WAS VERY CLEAN - NO SKIM OF OIL.

Chlorides 54,000 Oil Gravity 38

Describe Area Affected and Cleanup Action Taken.\*  
WELL LOCATION AND ADJACENT SPARSE VEGETATION PASTURE LAND - INDICATION OF STRESSED VEGETATION FROM PRIOR SURFACE DAMAGE

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: TEJAY SIMPSON	Approved by District Supervisor:	
Title: OPERATIONS SUPERVISOR	Approval Date: 7.25.07	Expiration Date: 9.10.07
E-mail Address tsimpson@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/24/2007 Phone: 396-4414 X 101	Full Delegation to	

'Clean' Required w/Plan  
FOR OGD APPROVAL BY

RP# 1499

\* Attach Additional Sheets If Necessary