

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	COG Operating LLC	Contact	Kanicia Carrillo
Address	550 W. Texas Ave, Ste 1300 Midland, TX 79701	Telephone No.	432-685-4332
Facility Name	Jalmat Yates Unit Battery	Facility Type	Tank Battery
Surface Owner	Mineral Owner	Lease No. 301048	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	13	25S	36E	1050	North	1100	East	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**


Type of Release	produced & fresh water leak	Volume of Release	600 bbls	Volume Recovered	Full recovery expected
Source of Release	Battery	Date and Hour of Occurrence	08/07/07 time unknown	Date and Hour of Discovery	8/06/07 apprx 9:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Hobbs NMOCD		
By Whom?	COG Pumper Warren Hunt	Date and Hour	9:00 am 08/07/07		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*  
*THIS SPILL OCCURED ON TOP OF A PREVIOUS SPILL THAT WAS IN THE PROCESS OF BEING CLEANED UP. REFER TO RP 1402*

Describe Cause of Problem and Remedial Action Taken.\*  
**Electrical failure caused the pumps to stop and the water was still flowing. Called for clean up.**

Describe Area Affected and Cleanup Action Taken.\*  
**Leak was contained within the battery. Immediate pick up and return to system. Highlander Environmental will turn in second report.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Kanicia Carrillo	Approved by District Supervisor: 		
Title: Regulatory Analyst	Approval Date: 8.8.07	Expiration Date: _____	
E-mail Address: kcarrillo@conchoresources.com	Conditions of Approval: _____		Attached <input type="checkbox"/>
Date: 08/07/07	Phone: 432-685-4332		

\* Attach Additional Sheets If Necessary

*RP # 1402*