

District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production Company,LP	Contact Jerry Mathews
Address P. O. Box 250, Artesia, NM 88210	Telephone No. <input type="checkbox"/> (505)748-5234
Facility Name Checkers 24 Fed# #1	Facility Type <input type="checkbox"/> Tank <input type="checkbox"/> Battery

Surface Owner FED - BLM	Mineral Owner	Lease No. <input type="checkbox"/> NMNM-81633
--------------------------------	---------------	--

LOCATION OF RELEASE

30.025.32849
32945

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	24	22S	32E	1980	South	1980'	East	Lea County, NM

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 130 bbls.	Volume Recovered <input type="checkbox"/> 125 bbls
Source of Release Rusted man way on steel tank	Date and Hour of Occurrence 8/19/2007	Date and Hour of Discovery <input type="checkbox"/> 8/19/2007 3 35pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? GARY WINK	
By Whom? <input checked="" type="checkbox"/> Angel Oroscio	Date and Hour <input checked="" type="checkbox"/> 3:35 PM 8/19/2007	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Man way rusted out on steel water tank causing water to spill out into containment dike. Having a new plate made, coat and inspect tank before installing plate.

Describe Area Affected and Cleanup Action Taken.*
Produced water was contained in dike on location. Called vacuum truck out to pick up produced water. Picked up 125 bbls. 5 bbls absorbed into gravel on location.
NEED CHLORIDE CONTENT OF WTR SPILLED ON ALL REPORTS.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Jerry Mathews	OIL CONSERVATION DIVISION	
Printed Name: Jerry Mathews	Approved by <input type="checkbox"/> District Supervisor: ENVIRONMENTAL ENGINEER	
Title: Production Foreman	Approval Date: 9.17.07	Expiration Date: 11.16.07
Date: August 22, 2007 Phone: (505)748-5234	Conditions of Approval: COMPLETE BY Attached <input type="checkbox"/>	



RP#1577