

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company CHEVRON USA INC.	Contact Larry Williams
Address P.O. Box 1949 Eunice NM. 88231	Telephone No. 505-394-1247 (office), 505-390-7165 (cell)
Facility Name- B.F. Harrison #16	Facility Type - SWD

Surface Owner- JEAN SALSMAN	Mineral Owner - State of New Mexico	Lease No.
-----------------------------	-------------------------------------	-----------

LOCATION OF RELEASE API # 3002532443

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	9	23S	37E	996	FNL	531	FWL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

WTR=80-90'

Type of Release- Produced water	Volume of Release 35 BW	Volume Recovered- 30 BW
Source of Release- 3" X 2' Steel nipple	Date and Hour of Occurrence- 08/16/2007 11:00 am	Date and Hour of Discovery 08/16/2007 11:15 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Pat Caperton	
By Whom? Larry Williams	Date and Hour 08/17/2007 11:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Internal corrosion inside of 3" steel riser going to disposal well. Picked up water off location and took to third party disposal.

Describe Area Affected and Cleanup Action Taken.* Fluid was contained on the well caliche pad. Standing fluid was picked up with vacuum truck. Location will be back dragged.
DEPTH TO GW=90 Chlorides 46,000

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Larry Williams</i>	OIL CONSERVATION DIVISION	
Printed Name: Larry Williams	Approved by District Supervisor: <i>J. Johnson</i>	
Title: Operations Rep	Approval Date: 9.17.07	Expiration Date: _____
E-mail Address: lcwl@chevron.com	Conditions of Approval: _____	
Date: 08/21/2007 Phone: 505-394-1247	Attached <input type="checkbox"/>	



* Attach Additional Sheets If Necessary

RPT# 578