

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Apache Corporation	Contact	John Good Elk Environmental
Address	P.O. Box 1849	Telephone No.	505-631-3277
Facility Name	Lockhart B-14 A No. 4	Facility Type	Battery API 30-025-06576
Surface Owner	Bill Stephens	Mineral Owner	
		Lease No.	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	14	21S	37E	1980	FSL	330'	FEL	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Unknown	Volume of Release	Unknown	Volume Recovered	Unknown
Source of Release	Unknown	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	Unknown
Was Immediate Notice Given?	Unknown <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Plains Pipeline had a pipeline leak, during there remediation, they uncovered the area that belonged to Apache. Elk Environmental was called out immediately. John Good with Elk Environmental has started the remediation process. This is a previous contaminated area. Currently they are digging and hauling the west side of the closed battery.

**RECEIVED**

Describe Area Affected and Cleanup Action Taken.\*

West side of old Battery, starting the remedial process, dig and haul in process.

JAN - 9 2008

**HOBBS OCD**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Approved by District Supervisor: <i>Pat Richardson</i> ENVIRONMENTAL ENGINEER	
Title: Environmental Tech	Approval Date: 1/9/08	Expiration Date: 3/9/08
E-mail Address: Natalie.gladden@usa.apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 01/09/08	Phone: 505-390-4186	

\* Attach Additional Sheets If Necessary

RP#1710