

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company - J Cleo Thompson	Contact - Jim Stevens
Address - P O Box 12577 Odessa, TX 79768	Telephone No. - 432-550-8887
Facility Name - Milnesand Unit #519	Facility Type - Flowline

Surface Owner - Private	Mineral Owner	Lease No.
-------------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	25	8S	34E	1980	FSL	660	FEL	Roosevelt

Latitude _____ Longitude _____

NATURE OF RELEASE


Type of Release - Oil	Volume of Release - Unknown	Volume Recovered - None
Source of Release - Flowline	Date and Hour of Occurrence ?	Date and Hour of Discovery 4-23-07 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Hobbs OCD	
By Whom? John Hughes - Foreman	Date and Hour 4-23-07 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* **N/A**


Describe Cause of Problem and Remedial Action Taken.* Flowline leaked at the pad of the Milnesand Unit #203 next to the abandoned well marker. MSU #203 is located at UL 'H' Sec.25 T8S R34E. Elke Environmental was called to look at spill and will have equipment onsite to remediate the spill within a week. **GW is greater than 100'**

Describe Area Affected and Cleanup Action Taken.* Area affected is 60' x 90' surface oil stain. Area is NOT used for cattle. Elke Environmental will delineate the spill and remediate according to NMOCD guidelines. A closure report will be submitted at the end of the job.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Logan Anderson	Approved by District Supervisor: 	
Title: Consultant	Approval Date: 5.1.07	Expiration Date: 7.1.07
E-mail Address: la_elkeenv@yahoo.com	Conditions of Approval: SUBMIT FINAL C-141	Attached <input type="checkbox"/>
Date: 4-24-07 Phone: 432-366-0043	W/SAMPLE DATA	

* Attach Additional Sheets If Necessary



100+

RP# 1736