

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company ConocoPhillips Company	Contact Jesse A. Sosa
Address 3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5	Telephone No. (505)391-3126
Facility Name Lockhart A27 Well #10	Facility Type Oil

Surface Owner BLM	Mineral Owner BLM	Lease No. LC032096A
-------------------	-------------------	---------------------

**LOCATION OF RELEASE**

API # 30025067950000

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	27	21S	37E	1980	North	1980	East	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release Oil	Volume of Release 14	Volume Recovered 10
Source of Release Flowline	Date and Hour of Occurrence 12/18/07 3:00 pm	Hour of Discovery 12/18/07 4
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD & BLM	
By Whom? Jesse Sosa	Date and Hour 12/19/2007 9:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

**RECEIVED**

JAN - 3 2008

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Tuesday December 18, 2007 at 3:00 pm an MSO found a spill at the Lockhart A27 Well #10 located 18 miles south of Hobbs NM. There was an accidental discharge of 14 BO from a flowline part due to stress and internal corrosion on 2 inch collar located on the line.

**HOBBS OCD**

Describe Area Affected and Cleanup Action Taken.\*  
Affected area was 15 feet X 140 feet. Leak was on caliche pad and road. MSO called a vacuum truck out and 10 BO was recovered. No cows were present. Area will be remediated in accordance with NMOCD and BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Jesse A. Sosa	 Approved by District Supervisor <b>ENVIRONMENTAL ENGINEER</b>	
Title: HSER Lead	Approval Date: 1-8-08	Expiration Date: _____
E-mail Address: Jesse.A.Sosa@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/19/2007	Phone: (505)391-3126	

\* Attach Additional Sheets If Necessary

Be sure and add API #  
to spill report if  
applicable. JHS,  
Pat

RP# 1705