

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849 Eunice, NM 88231	Telephone No. 505-390-4186
Facility Name NEDU #824	Facility Type Production
Surface Owner Charlie Bettis	Mineral Owner State
Lease No. 30-025-34800	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	22	21S	37E	1101	North Line	1522	East Line	Lea

Latitude 32 deg - 28.02 minutes Longitude W 103 Deg 8.63 minutes Elevation 3356

NATURE OF RELEASE

Type of Release Oil/Water	Volume of Release 80	Volume Recovered 70
Source of Release Nupi clamp connection	2/19/08	2/19/08 10:50 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson	
By Whom? Natalie Gladden	2/19/08 at 12:15pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

RECEIVED

FEB 21 2008

HOBBS OCD

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Nupi clamp connection busted causing the fluid to be released. Line was repaired, fluid was picked up, Emergency One Call placed and lines were pulled up on both sides of railroad tracks to start delineation.

Describe Area Affected and Cleanup Action Taken.*

East and West sides of railroad tracks, in culvert running West to East, were filled up with fluid. Elk Environmental on location in process of remedial action. NMOCD guidelines for remedial action will be followed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	<i>L. Johnson</i> Approved by District Supervisor ENVIRONMENTAL ENGINEER	
Title: Environmental Tech	Approval Date: 2.21.08	Expiration Date: 4.11.08
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/20/08 Phone: 505-390-4186	Submit Final C-141 w/ Documentation	IRP# 1792

* Attach Additional Sheets If Necessary

f COHD 805 255360