

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Apache Corporation	Contact Clayton Frank
Address P.O. Box 1849 Eunice, NM 88231	Telephone No. 505-390-0355
Facility Name WW Weatherly #7	Facility Type Production
Surface Owner Gary Deck	Mineral Owner State
API No. 30-025-36658	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	7	21S	37E	2310	North Line	1650	East Line	Lea

Latitude 32 deg - 28.766 minutes Longitude W 103 Deg 10.928 minutes Elevation 3494

NATURE OF RELEASE

Type of Release Oil/Water	Volume of Release 40bbls	Volume Recovered 30bbls
Source of Release Water Tank	2/24/08	2/24/08 3:43 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mark Whitaker	
By Whom? Natalie Gladden	2/24/08 at 7:40pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

WTR 80'

RECEIVED

FEB 26 2008

HOBBS OCD

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Automation system failed which caused water tank to overflow. Vacuum truck was called out and recovered 30bbls of fluid.

Describe Area Affected and Cleanup Action Taken.*

The battery is bermed and lined with 40 mil liner. All fluid was contained in battery. Hydro-tech will clean area on 2-27-08

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>		OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden		Approved by District Supervisor: <i>[Signature]</i>	
Title: Environmental Tech		Approval Date: 2-26-08	Expiration Date: 3-26-08
E-mail Address: natalie.gladden@apachecorp.com		Conditions of Approval:	
Date: 2/20/08 Phone: 505-390-4186		Submitted Final C-141 w/ Documents <input checked="" type="checkbox"/> Attached <input type="checkbox"/> IRP # 1795	

* Attach Additional Sheets If Necessary

PCOHO 805926475