

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

192403

Release Notification and Corrective Action

11 SEB 0806348922 OPERATOR Initial Report Final Report

Name of Company OXY USA WTP LP	Contact RICK KERBY, HES SPECIALIST
Address 102 S. Main St., POB 1988, Carlsbad, NM 88220	Telephone No. 505-887-8337
Facility Name SHELBY FEDERAL	Facility Type SATELLITE FACILITY
Surface Owner	Mineral Owner
	Lease No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	12	22 South	24 East					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Spill	Volume of Release 100 bbls oil 25bbls wtr	Volume Recovered 25 bbls oil 5 bbls wtr
Source of Release Frac tank ran over	Date and Hour of Occurrence 02/28/08 08:30a.m.	Date and Hour of Discovery 02/28/08 08:30a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, NMOCD Jim Amos, BLM	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
Not applicable

Describe Cause of Problem and Remedial Action Taken.*
Loss of pressure on vessel forced water to dump into frac tank. Frac tank ran over spilling contaminants onto location and into pasture.

Describe Area Affected and Cleanup Action Taken.*
Vacuum truck picked up standing liquid. Pads will be used to absorb isolated puddles. Water and soap will be used to wash contaminants to low spot to be picked up by vacuum truck. Micro blaze will be used over contaminated area. Area will be monitored to determine if further action will be necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rick Kerby</i>	OIL CONSERVATION DIVISION	
Printed Name: Rick Kerby	Approved by District Supervisor: <i>T Gum by SB</i>	
Title: HES Specialist	Process Date: <i>3-3-08</i>	Expiration Date: <i>N/A</i>
E-mail Address: rick.kerby@oxy.com	Conditions of Approval: REMEDIATION	Attached <input type="checkbox"/>
Date: 02/29/08 Phone: 505-887-8337 (O) 505-390-8639 (C)	WORK PLAN DUE BY APRIL 4, 2008	

* Attach Additional Sheets If Necessary

1 SEB 0806350156
1 SEB 0806350692

2RP-140