

District I - (505) 393-6161
 P. O. Box 1980
 Hobbs, NM 88241-1980
 District II - (505) 748-1283
 811 South First
 Artesia, NM 88210
 District III - (505) 334-6178
 1000 Rio Brazos Road
 Aztec, NM 87410
 District IV - (505) 827-7131

State of New Mexico
 Energy Minerals and Natural Resources Department
 Oil Conservation Division
 2040 South Pacheco Street
 Santa Fe, New Mexico 87505
 (505) 827-7131

Form C-141
 Originated 2/13/97

Submit 2 copies to
 Appropriate District
 Office in accordance
 with Rule 116 on
 back side of form

MAR 05 2008
 OCD-ARTESIA

ISEB0807030665 Release Notification and Corrective Action
 NSEB0806755979 OPERATOR Initial Report Final Report

| | |
|---|-------------------------------------|
| Name Transwestern Pipeline Co. 23435 | Contact Terry Younggren |
| Address 263 E. Four Dinkus Rd. | Telephone No. |
| Facility Name Atoka 3 | Facility Type Compressor Station |

| | | |
|--|---------------|-----------|
| Surface Owner Transwestern Pipeline Co. | Mineral Owner | Lease No. |
|--|---------------|-----------|

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| | 14 | 18 S | 26 E | | | | | Eddy |

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release Natural Gas | Volume of Release 2.415 mmcf | Volume Recovered None |
| Source of Release 2" Relief Valve | Date and Hour of Occurrence 2/28/08 00:30 | Date and Hour of Discovery 2/28/08 08:30 |
| Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | |
| By Whom? Karl McDonald | Date and Hour 3/5/08 14:30 | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

2" relief valve on fuel system of unit 842 failed in the open position and resulted in the release of the 2.415 mmcf of Natural Gas. Relief valve was cleaned and put back in service.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

Natural Gas was blown into atmosphere.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|-----------------------------|---|------------------------|---------------------------------------|
| Signature: Karl McDonald | OIL CONSERVATION DIVISION | | |
| Printed Name: Karl McDonald | Approved by District Supervisor: T. Cumby SB | Approval Date: 3-10-08 | Expiration Date: N/A |
| Title: AMT | Date: 3/5/08 | Phone: 746-2755 | Conditions of Approval: N/A |
| | | | Attached <input type="checkbox"/> N/A |

2RP-143