

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company Midland Operating	Contact Cam Robbins
Address 3100 North "A", Suite E-120 Midland TX 79705	Telephone No. 575-390-4677
Facility Name LMWU #116	Facility Type Flowline
Surface Owner Woolworth Est	Mineral Owner ?
Lease No. 2203199? API 30 025 1133A	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	28	24S	37E	660'	South	660'	East	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil & Water	Volume of Release 20bbls	Volume Recovered 15bbls
Source of Release Flow line	Date and Hour of Occurrence	Date and Hour of Discovery Feb28
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
LOCATION GIVEN IS FOR WELL # 307 API 30 025 1126 LEAK OCCURRED HERE FROM 116 LINE

Describe Cause of Problem and Remedial Action Taken.*
Hole in metal flow line, (corrosion), Shut well in & closed valves, installed emergency repair clamp on flow line to stop leak, called Vac. Truck & Recovered all fluid from ground, dig out saturated soil & haul to land farm, start bioremediation ASAP.

Describe Area Affected and Cleanup Action Taken.*
Area around flow line is 10' x 20', fluid ran East down trail 18" x 200' & pooled area 10' x 20', dug out saturated soil & hauled to land farm

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Victor Sirgo</i>	OIL CONSERVATION DIVISION	
Printed Name: Victor Sirgo	<i>J. Johnson</i> Approved by District Supervisor ENVIRONMENTAL ENGINEER	
Title: Owner/Operator	Approval Date: 3.27.08	Expiration Date: 5.27.08
E-mail Address:	Conditions of Approval:	
Date: 3-5-08 Phone: 432-638-5557	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

SUBMIT FINAL C.A.I. w/ DOCUMENTATION OF SAMPLES, BILLS OF LADEN FOR CONTAMINATED SOIL, COPY OF C-131 FROM RECIPIENT OF CONTAMINATED SOIL BY IRP # 1928 (NOTE THIS ON FINAL C-141) SHOW

FOHD 808737926