

New Mexico Energy, Minerals and Natural Resources Department

Bill Richardson

Governor

Joanna Prukop
Cabinet Secretary
Reese Fullerton
Deputy Cabinet Secretary

Mark Fesmire
Division Director
Oil Conservation Division



CERTIFIED MAIL—RETURN RECEIPT REQUESTED
7007 3020 0000 6292 9025

April 14, 2008

Jim Pierce/Phil Brewer
ATTN: Phil Brewer
PO Box 298
Roswell, NM 88202-0298

Reference: Mountain States Federal 1 P-35-18S-29E Eddy County, New Mexico
2RP-153

Operator,

The New Mexico Oil Conservation Division District 2 Office (OCD) is in receipt of a work plan proposal (plan) presented on behalf of operator by Eddie Seay Consulting for remediation of a release of produced fluids occurring at the above referenced facility. The plan proposes excavation and disposal of contaminated soils. After removal of contaminated soils, "...the area will be sampled for fluid cleanup and only after the OCD and BLM approval, we will backfill, level, and seed."

The plan is accepted with the following stipulations:

- Notify the OCD 48 hours prior to obtaining samples where analyses are to be submitted to the OCD.
- Results of analytical data obtained through sampling shall be forwarded to OCD for approval **prior to** any backfilling activities
- A final Report C-141 is to be submitted to the OCD upon satisfactory completion of remediation project.
- Remediation requirements may be subject to change as site conditions warrant.
- Remediation to be completed on or before May 30, 2008.

Please be advised that NMOCD acceptance of this plan does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of this plan does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

Respectfully,

Sherry Bonham
NMOCD District 2
1301 W Grand Avenue
Artesia, NM 88210
575.748.1283 ext. 109
sherry.bonham@state.nm.us

cc: Eddie W Seay, Eddie Seay Consulting
Paul Evans, BLM

Oil Conservation Division

1220 South St. Francis Drive • Santa Fe, New Mexico 87505
Phone (505) 476-3440 • Fax (505) 476-3462 • www.emnrd.state.nm.us/OCD



APR -3 2008
OCD-ARTESIA

**JIM PIERCE
MOUNTAIN STATE FED. #1
Unit P, Sect. 35, Tws. 18 S., Rng. 29 E.
GPS: 32 41' 51" N & 104 02' 22" W
Eddy Co.**

WORKPLAN

**Prepared By
Eddie Seay Consulting
April 2008**

2pp-153

April 1, 2008

NMOCD Environmental
ATTN: Mike Bratcher
1301 W. Grand Ave.
Artesia, NM 88210


RE: Jim Pierce
Mountain State Fed. #1
Spill

Mr. Bratcher:

At the request of Phil Brewer, the administrator for the Jim Pierce properties, I have been requested to file a workplan and coordinate the remediation for the above listed spill. The spill was stabilized and all corrections made to prevent further problems.

Attached is workplan for your approval. Should you have any questions, please call.

Thanks,



Eddie W. Seay, Agent
Eddie Seay Consulting
601 W. Illinois
Hobbs, NM 88242
(575)392-2236
seay04@leaco.net

cc: BLM, Paul Evans

WORKPLAN

General:

On or about February 20, 2008, the fiberglass production water tank ran over due to the failure and the transfer pump not coming on. Approximately 22 bls. of water wan over tank into pasture affecting an area of 90' x 30'. Area was stabilized and soil partially picked up.

Groundwater:

According to the water information, the depth to groundwater occurs at approximately 180 ft. from ground surface.

Remediation Proposal:

All available fluid was picked up and saturated soil. Our cleanup proposal will be to excavate and haul the contaminated soil to an OCD approved facility. After contaminated soil has been removed, the area will be sampled for fluid cleanup and only after the OCD and BLM approval, we will backfill, level and seed. We will file a final report after closing.

Ranking Criteria Score: 0

Groundwater at 180 ft., no surface water or waterways. The site has a 5000 ppm cleanup level for TPH and will clean up chloride per OCD.

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

GAST, GUTH ET AL.

2017-06-2

320 E GREENE STREET
CARBONDALE, ILLINOIS

2001-187 C 4559
KUS 47 N166.203

卷之三

| Banks | | | | | | | | |
|-----------------|-------------|-----------|----------|-----------|------------|--------------|-----------|-------------|
| Bank | Capital | Deposits | Reserves | Loans | Securities | Other Assets | Equity | Liabilities |
| MONTEVIDEO BANK | \$1,250,000 | 1,250,000 | 250,000 | 1,000,000 | 500,000 | 100,000 | 1,250,000 | 1,250,000 |
| URUGUAYAN BANK | \$1,000,000 | 1,000,000 | 200,000 | 800,000 | 400,000 | 100,000 | 1,000,000 | 1,000,000 |

Journal of Oral Rehabilitation 2003; 30: 103–109. © 2003 Blackwell Publishing Ltd

| Time | Location | Date | Notes |
|-------|------------|---------------------------------|-------|
| 09:45 | 03/21/2016 | Wetland area, 100' E of Hwy 101 | |

2/20/07

not have replaced it previously.

2/24/18

2/19/08

Digitized by srujanika@gmail.com

LEASE OPERATOR

~~3/13/19~~

We are in process in becoming an Accredited Firm. We have
done our audit and expect to have this build up soon.

The author(s) received no financial support or material aid in connection with this study.

Section 3 of the bill would prohibit the disclosure of information held by SIIA as an exempt, confidential or privileged record under the FOIA, unless specifically authorized by statute.

Keywords and Appendix Rights

¹ The second author wishes to thank the Director of the National Statistical Bureau of Sri Lanka for his permission to publish this paper.

John C. Green

2/18/1990

مکتبہ

FOR OFFICE USE ONLY

18

DEERFIELD
1625 N French Dr., Hobbs, NM 88240
Office: 505-432-1100
1301 W Grand Avenue, Artesia, NM 88210
District Office
1000 Rio Bravo Blvd., Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2002
Submit 2 copies to appropriate
District Office in accordance
with Rule 11C on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report

Final Report

| | | | |
|-----------------|---------------------------------|---------------|---------------------------|
| Name of Company | Sierra Pierce | Contact | Willie DEAN / PHIL Brewer |
| Address | 200 W 1st BISSELL NM 88201-4851 | Telephone No. | 505-432-5010 505-425-0298 |
| Facility Name | MOUNTAIN STATES | Facility Type | TANK BATTERY |
| Surface Owner | BLM - SEACREST | Mineral Owner | BLM - US GOVERNMENT |
| | | | Lease No. |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| P | 35 | 18 | 292 | 330 | FSL | 990 | FEL | EDDY |

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|---------|----------------------------|---------|
| Type of Release | SOLID | Volume of Release | 22 | Volume Recovered | 2 |
| Source of Release | 1500 GALLONS IN TANK | Date and Hour of Occurrence | 3-19-08 | Date and Hour of Discovery | 3-19-08 |
| Was Immediate Notice Given? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | | | |
| By Whom? | Date and Hour | | | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.

Describe Cause of Problem and Remedial Action Taken.* Power was found to be turned off on 3-19-08 causing the pressurized water transfer pump NOT TO BE RUNNING. THE FILLING ASS PUMP, RAN OVER INTO THE pastures causing the release.

Describe Area Affected and Cleanup Action Taken.* The pasture behind the tank battery. The dirt/mud soil was picked up, some was hauled off, and some of the soil was utilized to extend the pad for the SWD tank and sand was used for a dike.

* I certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability if their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: William K Dean

Approved by District Supervisor:

Printed Name: WILLIAM K DEAN

Approved Date:

Expiration Date:

Title: EPA OPERATOR (Pumper)

Approval Date:

Expiration Date:

E-mail Address: EPA.PUMPING@FBI.GOV


Conditions of Approval:

Attached:

Date: 3/13/08

Phone: 505-631-5612

* Attach Additional Sheets if Necessary



Groundwater

