

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production Company, L.P.	Contact Roger Hernandez
Address P. O. Box 250, Artesia, NM 88210	Telephone No. <input type="checkbox"/> (505) 748-5239
Facility Name Panther Martin	Facility Type <input type="checkbox"/> Gas Well

Surface Owner <u>PRIVATE</u>	Mineral Owner	Lease No. <input type="checkbox"/>
------------------------------	---------------	------------------------------------

LOCATION OF RELEASE

Unit Letter	Section 3	Township 16S	Range 35E	Feet from the 2310	North/South Line South	Feet from the 1650	East/West Line West	County Lea County
-------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------------

NATURE OF RELEASE


Type of Release Condensate and Produced Water	Volume of Release 102	Volume Recovered <input type="checkbox"/> 32 bbls.
Source of Release Frozen valve line	Date and Hour of Occurrence January 2, 2008 10:30 AM	Date and Hour of Discovery <input type="checkbox"/> January 2, 2008 9:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD - Pat Richards	
By Whom? <input type="checkbox"/> Roger Hernandez	Date and Hour <input type="checkbox"/> January 2, 2008 9:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
BS line froze and split valve resulting in release of 102 total bbls. (67 bbls of condensate and 35 bbls produced water). Complete remediation report attached. Remediated by Whole Earth Environmental.

Describe Area Affected and Cleanup Action Taken.*
80% of spill contained on well pad and area 4'x150' off location on East side. Attached Remediation Report.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION 	
Printed Name: Don Mayberry	Approved by <input type="checkbox"/> District Supervisor ENVIRONMENTAL ENGINEER	
Title: SENM Superintendent	Approval Date: 3.12.08	Expiration Date: _____
Date: February 26, 2008 Phone: (505) 748-5239	Conditions of Approval: _____	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

FOH 081265 6028

IRP # 1812