

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

192463 **Release Notification and Corrective Action**

SEB0812648306
SEB0812648097

OPERATOR Initial Report Final Report

Name of Company OXY USA WTP LP	Contact Rick Kerby
Address PO Box 1988 102 S Main Carlsbad NM 88220	Telephone No. (O) 505-887-8337 (C) 505-631-4972
Facility Name Mckittrick Hill CTB	Facility Type Indian Basin
Surface Owner	Mineral Owner
Lease No.	

30-015-21010 **LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	14	22 S	24 E					EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Oil	Volume of Release 132.48	Volume Recovered 0
Source of Release Oil Leak	Date and Hour of Occurrence 10:00 AM	Date and Hour of Discovery 10:30 AM
Was Immediate Notice Given? Required <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? Mike Bratcher NMOCD Jim Amos BLM	
By Whom? Rick Kerby	Date and Hour 1:40 PM 5-1-2008	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken * Hole in the bottom of the tank allowed fluid to leak out on the ground. All fluid contained inside secondary containment.		
Describe Area Affected and Cleanup Action Taken.* All fluid contained inside berm and work plan will be formulated and forwarded to appropriate government agencies		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Rick Kerby</i>	OIL CONSERVATION DIVISION	
Printed Name: Rick Kerby	Approved by District Supervisor: <i>Rumby SB</i>	
Title: HES Tech	Approval Date: <i>5-5-08</i>	Expiration Date:
E-mail Address: rick.kerby@oxy.com	Conditions of Approval: <i>REMEDIATION</i>	Attached <input checked="" type="checkbox"/>
Date: 4-11-08 Phone: 631-4972	<i>WORK PLAN DUE by 6-9-08</i>	

* Attach Additional Sheets If Necessary
SEB0812648426
SEB0812648690

2RP-163

New Mexico Energy, Minerals and Natural Resources Department

Bill Richardson
Governor

Joanna Prukop
Cabinet Secretary
Reese Fullerton
Deputy Cabinet Secretary

Mark Fesmire
Division Director
Oil Conservation Division



May 5, 2008

OXY USA WTP LP
PO Box 1988
Carlsbad, NM 88220

Reference: McKittrick Hill Central Tank Battery H-14-22S-24E
API: 30-015-21010 Eddy County New Mexico
2RP-163

Operator,

The New Mexico Oil Conservation Division District 2 Office (OCD) is in receipt of an Initial Report Form C-141 reporting a release of crude oil that occurred on or about May 1, 2008 at the above referenced tank battery. Please submit a work plan proposal (plan) for remediation, removal and/or clean up of contaminants that may be present at this site. The plan is to be formulated based on vertical and horizontal delineation of contamination, site ranking, and OCD Rules and Guidelines.

A publication outlining OCD guidelines and requirements for site ranking and spill remediation can be found on the OCD website as follows: <http://www.emnrd.state.nm.us/oed/index.htm> Click on each of the following items as they appear:

- Publications
- Environmental Handbook
- Miscellaneous Guidelines
- Remediation of Leaks, Spills and Releases

Please submit this plan to the OCD District 2 office on or before **June 9, 2008**. Please include any remedial or clean up actions that have already been performed.

Please be advised that NMOCD acceptance and/ or approval of documents or work plans does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance and/or approval of documents or work plans do not relieve the operator of responsibility for compliance with any other federal, state, local laws and /or regulations.

Should you have any questions, or if I can be of assistance, please contact me.

Sincerely,

A handwritten signature in black ink, appearing to read "Sherry Bonham", is written over a horizontal line.

Sherry Bonham
NMOCD District 2
1301 W Grand Ave.
Artesia, NM 88210
(505) 748-1283 Ext.109

