

XDistrict I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Avenue, Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources

Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised October 10, 2003

Submit 2 Copies to appropriate
 District Office in accordance
 with Rule 116 on back
 side of form

Release Notification and Corrective Action

OPERATOR

X Initial Report Final Report

Name of Company	BC Operating, Inc	Contact	Gary Stevens
Address	P O Box 50820 Midland, TX 79710	Telephone No.	432-894-7113
Facility Name	Angell #1	Facility Type	tank battery
Surface Owner	Darr Angell	Mineral Owner	
		Lease No. 30-025-37902	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	11	17S	36E	660	North	660	East	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	oil	Volume of Release	20 bbls	Volume Recovered	18 bbls
Source of Release	tank overflow at battery	Date and Hour of Occurrence	4/22/08	Date and Hour of Discovery	4/22/08
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mark Whitaker		
By Whom?	Pam Botkin	Date and Hour	4/23/08	9:30 am	
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.			

RECEIVED

APR 28 2008

HOBBS OCD

Describe Cause of Problem and Remedial Action Taken.*

Tank overflow, recovered with vacuum truck

Describe Area Affected and Cleanup Action Taken.*

Spill was contained inside the fire wall at battery. Recovered oil, scooped up dirt, hauled off.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Pam Botkin</i>	OIL CONSERVATION DIVISION	
Printed Name: Pam Botkin	Approved by District Supervisor: <i>[Signature]</i>	
Title: Engineering Tech	Approval Date: 4.30.08	Expiration Date: 6.30.08
E-mail Address: pbotkin@usaonline.net	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 04/23/08 Phone: 432-684-9696 x 216	SUBMIT FINAL C-141 W/ VERTICAL DELINEATION REPORT BY (TPH & CHLORIDE) IRP# 1849	

* Attach Additional Sheets If Necessary

FOH 0812731351