

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources.

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Forest Oil	Contact: Rick Rickman
Address: 3504 NW County Rd., Hobbs, NM 88240	Telephone No.: 575-392-9827
Facility Name: CMU C Battery	Facility Type: Tank Battery

Surface Owner: State of New Mexico	Mineral Owner	Lease No. CMU C Battery
------------------------------------	---------------	-------------------------

LOCATION OF RELEASE

Ref: *API-30-025-01530*
CMU-91

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County LEA
	28	17S	33E					

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: unknown	Volume Recovered: unknown
Source of Release: flowline	Date and Hour of Occurrence: na	Date and Hour of Discovery: na
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson-NMOCD	
By Whom? Kelton Beard/ Hungry Horse Environmental	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

RECEIVED

JUN 12 2008



HOBBS OCD

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The flowline coming out of the treater leaked. There was no standing fluids on the ground, immediate remediation was done.

Describe Area Affected and Cleanup Action Taken.*
An area just north of the battery approx. 140' X 40' was affected. 2 foot of the ground was remediated, where TPH and BTEX samples were shown to be below the limits per OCD approval. A drilling rig was brought in to drill bore holes to determine where the chloride limit was. The depth of the chlorides showed to be below 250ppm @ 65'bgs. Approval was given from the OCD to line the area with a 12 ml. liner and backfill the area with clean topsoil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kelton Beard	Approved by:  District Supervisor	
Title: Environmental Technician	ENVIRONMENTAL ENGINEER	
E-mail Address: k.beard@hungryhorseenvironmentalservices.com	Approval Date: 6-12-08	Expiration Date: _____
Date: 4-22-08 Phone: 575.631.1665	Conditions of Approval:	RP Attached <input type="checkbox"/> LRP-1878

* Attach Additional Sheets If Necessary

FOHO 816536841