

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company DCP Midstream, LP	Contact Johnnie Bradford
Address # 10 Desta Drive, Suite 400 W, Midland, TX 79705	Telephone No. & E-mail 432.620.4166 jbradford@dcpmidstream.com
Facility Name "F" Line	Facility Type Pipeline ("F" Line)
Surface Owner	Mineral Owner
Lease No. 30-025-3712	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	20 30	20 16S	37 34E		S		E	LEA

Latitude 32 55.867 Longitude 103 270.70

NATURE OF RELEASE

Type of Release Liquids and Sour Gas	Volume of Release 6.5 bbls	Volume Recovered 4.5 bbls
Source of Release Hole in Pipeline	Date and Hour of Occurrence NA	Date and Hour of Discovery 06/24/2008 1500 hrs.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD Chris Williams by telephone (voice message)	
By Whom? Johnnie Bradford	Date and Hour 02/28/2007 10:00	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	

If a Watercourse was Impacted, Describe Fully.*

NA

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

Area above a DCP pipeline was discovered by DCP personnel to be wet with hydrocarbon liquids. The Field Operator notified his supervisor who promptly dispatched a vacuum truck to remove any free liquids from the site. A remediation contractor was contacted to survey site and to begin the process of soil remediation.

JUN 26 2008
HOBBS OCD

Describe Area Affected and Cleanup Action Taken.*

The area affected was the "F" Pipeline right of way (two tracker road). The approximate size of the affected area is approximately 2' wide x 60' long x 4" deep. All effected soils will be tested for TPH and BTEX (process knowledge constituents of DCPM pipeline), remediated, and hauled to an NMOCD approved disposal site. After all contaminated soil is removed; this location will be backfilled with soil approved by the NMOCD. *CI-CW*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Johnnie Bradford by CW 6/27/08</i>	OIL CONSERVATION DIVISION	
Printed Name: JOHNNIE BRADFORD	Approved by District Supervisor: <i>Chris Williams</i>	
Title:	Approval Date: <i>6/26/08</i>	Expiration Date: <i>8/26/08</i>
E-mail Address: <i>jbradford@dcpmidstream.com</i>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>6/26/08</i>	Phone:	<i>LRP-1886</i>

FCOHD0817 940975