

District I
1625 N. French Dr., Hobbs, NM 88210
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

SEB0819333664
N SEB0819331936

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Facility Name Medano VA State #1	Telephone No. 505-748-1471
Facility Name Medano VA State #1	API Number 30-015-20423	Facility Type Battery
Surface Owner State	Mineral Owner State	Lease No. VO-0120

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	16	23S	31E	1980	South	1980	West	Eddy

Latitude 32.30252 Longitude 103.78442

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 300 B/PW	Volume Recovered 150 B/PW
Source of Release Pipe Line	Date and Hour of Occurrence 6/16/2008, AM	Date and Hour of Discovery 6/16/2008, AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD District II (Voicemail & E-mail)	
By Whom? Robert Asher/YPC Environmental Department	Date and Hour 6/16/2008, PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Main 6" line behind battery ruptured causing release. Shut down well (s), called vacuum truck and repaired line.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 125' X 12'. Vacuum truck picked up remaining produced water. This release area overlaps with the 4/9/2008 release, and Yates requests remediation work to be included under the work plan approved 6/5/2008. Depth to Ground Water: >100' (approx. 125'), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature:	Approved by District Supervisor:		Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date.
Printed Name: Robert Asher	Approval Date: <u>7-11-08</u>	Expiration Date: <u>9-12-08</u>	
Title: Environmental Regulatory Agent	Conditions of Approval: Notify OCD 48 hours prior to obtaining samples where analyses are to be presented to OCD		Attached <input type="checkbox"/> <u>2RP-160</u>
E-mail Address: hoba@ypcnm.com			
Date: Friday, June 20, 2008 Phone: 505-748-1471			

* Attach Additional Sheets If Necessary

SEB081933717