

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JUN 02 2008
OCD-ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

SEB0821737244
NSEB0821736965

OPERATOR

Initial Report Final Report

Name of Company	St. Mary Land & Exploration 154903	Contact	Tom Morrow
Address	3300 N. A. St. Bldg 7, Suite 700, Midland, TX 79705	Telephone No.	432-688-1773
Facility Name	Blackhawk Federal #5	Facility Type	

Surface Owner	Bureau of Land Management	Mineral Owner	Bureau of Land Management	Lease No.	LC - 065680
---------------	---------------------------	---------------	---------------------------	-----------	-------------

30-015-25651

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	23	18S	31E	2310	South	330	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil/Produced Water	Volume of Release	2 BO. 12BW	Volume Recovered	0 bbls
Source of Release	2" Flowline	Date and Hour of Occurrence	05/27/08 5:00AM	Date and Hour of Discovery	05/27/08 6:30 AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required				
By Whom?	If YES, To Whom?				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
If YES, Volume Impacting the Watercourse.					

If a Watercourse was Impacted. Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Cause: Flowline pressured up – slightly plugged
Remedial Action Taken: Repaired flowline

Describe Area Affected and Cleanup Action Taken.*
70' X 50' (slight spray)
Dug up soil with Backhoe and hauled to CRI. Replaced with fresh soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Donna Huddleston</i>	OIL CONSERVATION DIVISION		
Printed Name: Donna Huddleston	Approved by District Supervisor: <i>TEum by SB</i>		
Title: Production Tech	Approval Date: <i>8-4-08</i>	Expiration Date: <i>N/A</i>	
E-mail Address: dhuddleston@stmaryland.com	Conditions of Approval: <i>N/A</i>		Attached <input type="checkbox"/> <i>N/A</i>
Date: 5/30/08	Phone: 432-688-1789		

* Attach Additional Sheets If Necessary

2PP-203