

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849 Eunice, NM 88231	Telephone No. 505-390-4186
Facility Name Nedu Sat 4A (Nedu #902 nearest well)	Facility Type Gathering Line
Surface Owner Deck	Mineral Owner BLM
Lease No. 30-025-06752	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	22	21S	37E	2080'	South Line	1650'	West Line	Lea

Latitude \_N32 deg 27.767'\_ Longitude \_W103 deg 09.252'

**NATURE OF RELEASE**

Type of Release Hydrocarbon/Produced Water	Volume of Release 50bbls	Volume Recovered 46bbls
Source of Release Gathering Line	Occurrence 09/2/08 5:25 pm	Discovery 09/02/08 5:25 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson	
By Whom? Natalie Gladden	Date and Hour 09/02/08 6:04pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Southern Union was repairing a line when they struck Apache's gathering line. Production was shut in, 46bbbs of fluid was recovered from ditch. All fluids were contained in ditch.

Describe Area Affected and Cleanup Action Taken.\*

All contaminates were dug out and line was repaired.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Natalie Gladden	Approved by District Supervisor: 	
Title: EH&S Environmental Tech	Approval Date: 9.15.08	Expiration Date: 11.15.08
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval: SUBMIT FINAL C. #1	Attached <input type="checkbox"/> IRP-1951
Date: 09/03/08 Phone: 505-390-4186		

\* Attach Additional Sheets If Necessary

FQRL0826257267