

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Apache Corporation	Contact Natalie Gladden
Address P.O. Box 1849 Eunice NM 88231	Telephone No. 505-390-4186
Facility Name NEDU #102	Facility Type Injection Well

Surface Owner McCasland	Mineral Owner BLM/State	Lease No. 30-025-06400
-------------------------	-------------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	2	21S	37E	1582	North Line	990	East Line	Lea

Latitude N 32 deg 31.074' Longitude W 103 deg 09.765'

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 60-70bbls	Volume Recovered 50bbls
Source of Release Injection line leak	Occurrence 09/02/08 Unknown	Discovery 09/2/08 12:13 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson	
By Whom? Natalie Gladden	Date and Hour 09/02/08 1:15pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A small pin hole was found in 2" elbow 4' under ground. Vacuum truck was called out and recovered 50bbls of produced water. Well was shut in until fixed.

Describe Area Affected and Cleanup Action Taken.*

All produced water was released onto location. 12" of chloride impacted soil has been picked up and hauled to Sundance. We will remediate the entire site once bidding process has occurred. NMOCD guidelines will be followed to closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Approved by District Supervisor: 	
Title: EH&S Environmental Tech	Approval Date: 9.15.08	Expiration Date: 11.15.08
E-mail Address: natalie.gladden@apachecorp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09/02/08 Phone: 505-390-4186	SUBMIT FINAL C-141	IRP 195Z

* Attach Additional Sheets If Necessary