

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Plains Pipeline, LP	Contact	Daniel Bryant
Address	P.O. Box 3119 - Midland, Tx 79702	Telephone No.	(432) 557-5865
Facility Name	Jal Tank Farm Tank 1214	Facility Type	Tank Farm

Surface Owner	Plains	Mineral Owner		Lease No.	
---------------	--------	---------------	--	-----------	--

**LOCATION OF RELEASE**

API# 30.025.11955.00.00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	5	26S	37E					Lea

Latitude N 32.07884° Longitude W 103.17952°

**NATURE OF RELEASE**

Type of Release	Crude Oil	Volume of Release	200 bbls	Volume Recovered	190 bbls
Source of Release	Tank 1214 at Jal Tank Farm	Date and Hour of Occurrence	09/12/2008	Date and Hour of Discovery	09/12/2008 05:30
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Larry Johnson (left message)		
By Whom?	Daniel Bryant	Date and Hour	09/15/2008 09:30	<b>RECEIVED</b>	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully.\*

OCT 01 2008  
HOBBS OCD



Describe Cause of Problem and Remedial Action Taken.\*

Heavy rain overwhelmed partially blocked roof drain during extremely heavy rain storm. 2 roof drains were stopped up. Drains were cleared & draining proceeded but at some point the roof on tank 1214 flooded with oil causing release of approx. 200 bbls. on ponded rainwater inside firewall.

Describe Area Affected and Cleanup Action Taken.\*

All released materials were contained inside the secondary containment. Area will be remediated per applicable guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Daniel Bryant	 Approved by District Supervisor <b>ENVIRONMENTAL ENGINEER</b>	
Title: Environmental R/C Specialist	Approval Date: 10.1.08	Expiration Date: 12.1.08
E-mail Address: dmbryant@paalp.com	Conditions of Approval:	
Date: 9/26/08 Phone: (432) 557-5865	Attached <input type="checkbox"/> <b>SUBMIT FINAL C-141</b> <b>RP# 1961</b>	

\* Attach Additional Sheets If Necessary

w/Docs BY 12.1.08

FGRL 0828051101