

1625 N. French Dr., Suite 100, Midland, TX 79705
 1701 W. Grand Avenue, Albuquerque, NM 87102
 1000 Alameda Road, Santa Fe, NM 87505
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised October 15, 2000
 Submit 1 Copy to appropriate
 District Office in accordance
 with Rule 116 on back
 side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Duke Energy Field Services, LP
 Address: 10 Dean Dr., Suite 400-W, Midland, TX 79705
 Facility Name: RR East Low Pressure Gathering Line
 Contact: Lynn Ward/Polo Rendon
 Telephone No.: 432/626-4207 or 505/390-3704
 Facility Type: Low Pressure Gathering Pipeline

Surface Owner: STATE Mineral Owner: Lease No.:

LOCATION OF RELEASE

API # 30.025.06182

Unit Loc.	Section	Township	Range	Foot from Gr.	North/South Line	Foot from Gr.	East/West Line	County
NEW	19	20S	37E					Lea County
C		20S	37E					Lea County

Latitude: 32.5634 Longitude: -103.29174

NATURE OF RELEASE

Type of Release: Pipeline Leakage Release	Volume of Release: 30 bbls	Volume Recovered: 20 bbls
Source of Release: A subsea low pressure pipeline	Date and Hour of Occurrence: 12/13/08 unknown	Date and Hour of Discovery: 12/13/08 @ 11:15 am MST
Was Immediate Notice Given?	If YES, To Whom?	
☒ Yes ☐ No ☐ Not Required	Larry Johnson, NMOCED, Hobbs, NM	
By Whom? Kevin Verbeke	Date and Hour: 12/13/08 @ 3:15 pm MST	
Was a Watchman Reached?	If YES, Volume Impacting the Watchman:	
☐ Yes ☒ No	NA	

If a Watchman was Impacted, Describe Fully:

NA

Describe Cause of Problem and Remedial Action Taken:

Trained personnel from normal daily operations caused degradation of the pipeline steel and a release of 30 bbls of condensate. The release was discovered at 11:15 am MST. The pipeline was depressurized and a clamp used to terminate the release. Visual notification was made by Lynn Ward to Larry Johnson of the NMOCED in Hobbs, NM. The line has been taken out of service and scheduled for replacement.

Describe Any Cleanup and Cleanup Action Taken:

LINE LEAK 30 BBS COST
 LINE TAKEN OUT OF SERVICE
 WILL HAVE NEW REPLACEMENT

Duke Energy Field Services, LP will contract with Environmental Plus, Inc. of Bunkie, NM to delineate and remediate the release site. The release will be remediated consistent with the NMOCED guidance for the remediation of spills. Remedial goals will be determined based on the depth to groundwater and a remediation plan will be developed and submitted to the NMOCED for approval prior to remedial activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCED rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCED as a "Final Report" does not relieve the operator of liability should their operations prove to be inadequately investigated and remediate contamination that poses a threat to ground water, surface water, human health or the environment. In addition, NMOCED acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and regulations.

Signature: <i>Lynn Ward</i>	OIL CONSERVATION DIVISION	
Printed Name: Lynn Ward	Approved by District Supervisor: <i>L. Johnson</i>	
Title: Environmental Specialist	ENVIRONMENTAL ENGINEER	
E-mail Address: lward@duke-energy.com	Approval Date: 11.7.08	Expiration Date: 1.7.09
Date: 1/3/09	Phone: 432/626-4207	Conditions of Approval:
		Attached: ☐ IRP 1999

FGRL0834336457