

575-748-9720

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NSC80900242059 154303 OPERATOR Initial Report Final Report

Name of Company	PRIMAL ENERGY CORP.	Contact	TRAVIS WILSON	WILLIE DEAN
Address	211 HIGHLAND CROSS SUITE 227	Telephone No.	575-390-1921	575-631-5010
Facility Name	BIG EDDY #132	Facility Type	OIL WELL	
Surface Owner		Mineral Owner	Lease No.	
STATE				

01527778

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	16	21S	29E					EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	OIL + WATER	Volume of Release	5 BBL	Volume Recovered	NONE
Source of Release	WELL HEAD	Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		TRAVIS WILSON WILLIE DEAN			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Date and Hour			
		If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
WELL HEAD NIPPLE CRACK AND STUFFING BOX
REPLACE NIPPLE AND REPAIR STUFFING BOX.
CLEAN UP AREA DUG FOR BACKHOE.

Describe Area Affected and Cleanup Action Taken.*
BACKHOE DUG UP AREA AROUND LOCATION AND UNIT.
CARRY CONTAMINATED SOIL TO LAND FARM. TOOK SOIL
SAMPLES TO LAB.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>William R Dean</i>	OIL CONSERVATION DIVISION	
Printed Name: WILLIAM R DEAN	Accepted for record NMOCD	
Title: LEASE OPERATOR	Approved by District Supervisor:	Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date
E-mail Address: DEANSPUMPING@AOL.COM	Approval Date:	Expiration Date: March 2, 2009
Date: 12-7-08 Phone: 575-631-5010	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
	STIPULATIONS	2RP-286

* Attach Additional Sheets If Necessary





PHONE (575) 383-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
 CWS BACKHOE SERVICE
 ATTN: C. W. MOTES
 1118 14TH STREET
 EUNICE, NM 88231
 FAX TO: (575) 384-0132

Receiving Date: 11/26/08
 Reporting Date: 12/01/08
 Project Number: BIG EDDY
 Project Name: NOT GIVEN
 Project Location: EDDY COUNTY, NM

Sampling Date: 11/26/08
 Sample Type: SOIL
 Sample Condition: INTACT
 Sample Received By: AB
 Analyzed By: AB/ZL

LAB NUMBER/SAMPLE ID	BENZENE (mg/kg)	TOLUENE (mg/kg)	ETHYL BENZENE (mg/kg)	TOTAL XYLENES (mg/kg)
ANALYSIS DATE	11/30/08	11/30/08	11/30/08	11/30/08
H16432-1 DIRTY	0.388	1.80	4.46	13.5
H16432-2 CLEAN	<0.050	0.068	0.068	0.505
Quality Control	0.042	0.045	0.043	0.134
True Value QC	0.050	0.050	0.050	0.150
% Recovery	84.0	90.0	86.0	89.3
Relative Percent Difference	6.8	2.1	1.1	0.7

METHOD: EPA SW-846 8021B

TEXAS NELAP CERTIFICATION T104704398-08-TX FOR BENZENE, TOLUENE, ETHYL BENZENE, AND TOTAL XYLENES.

Chemist

Date

H16432 B CWBS

PLEASE NOTE Liability and Damages: Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.



PHONE (575) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
 CWS BACKHOE SERVICE
 ATTN: C.W. MOTES
 1118 14TH ST.
 EUNICE, NM 88231
 FAX TO: (575) 394-0132

Receiving Date: 11/26/08
 Reporting Date: 12/02/08
 Project Number: BIG EDDY
 Project Name: NOT GIVEN
 Project Location: EDDY COUNTY, NM

Sampling Date: 11/26/08
 Sample Type: SOIL
 Sample Condition: INTACT
 Sample Received By: AB
 Analyzed By: AB

LAB NUMBER SAMPLE ID	GRO	DRO
	(C ₉ -C ₁₀) (mg/kg)	(>C ₁₀ -C ₂₈) (mg/kg)
ANALYSIS DATE:	12/01/08	12/01/08
H16432-1 DIRTY	2,830	30,200
H16432-2 CLEAN	<10.0	15.4
Quality Control	595	515
True Value QC	500	500
% Recovery	119	103
Relative Percent Difference	3.3	2.3

METHOD: SW-846 8015 M

Lab Director

12/02/08
 Date

H16432 T CWBS

PLEASE NOTE: Liability and Damages: Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for employee services. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise. Results relate only to the sample identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.



ARDINAL LABORATORIES

101 East Merland, Hobbs, NM 88240
(575) 393-2326 Fax (575) 393-2476

Company Name: W. MOTES

Project Manager: W. MOTES

Address: 1118 14th St

City: BUNICE State: NM Zip: 88231

Phone #: 575-605-2292 Fax #: 398 0921

Project #: R16 EDDY Project Owner: 0132

Project Name: _____

Project Location: EDDY COUNTY

Sampler Name: LARRY MOTES

PO #: _____

Company: PRIMA COMPANY

Address: 21021 Snybrook Plaza

City: Spring

State: TX Zip: 75377

Phone #: _____

Fax #: _____

ANALYSIS REQUEST

Lab I.D.	Sample I.D.	(G/RAB OR C/OMP)	# CONTAINERS	GROUNDWATER	WASTEWATER	SOIL	OIL	SLUDGE	OTHER	ACID/BASE	ICE / COOL	OTHER	DATE	TIME	TPH	BTEX
<u>1116-932-1</u>	<u>DIRTY</u>		<u>2</u>			<u>X</u>							<u>11/24/18</u>		<u>X</u>	
	<u>-2</u>															
	<u>clean</u>															

URGENT NOTE: Unless you contact Cardinal directly and clearly indicate a need for any data, we are unable to conduct or test. It is the customer's responsibility to provide the correct information for the appropriate analysis. All data resulting from this report is for informational purposes only. It is not intended to be used for legal or regulatory purposes. In no event shall Cardinal be liable for incidental or consequential damages, including lost profits, arising out of the use of the information provided herein. The user of this information assumes all liability for any use of the information provided herein.

Sampler Requisitioned: _____ Date: 11/21/18 Received By: _____

Refill/replace head by: _____ Date: 11/30/18 Received By: CB

Delivered By: (Circle One) _____ Temp: _____ Sample Condition: _____ CHECKED BY: _____

Sampler - UPS - Bus - Other: _____ Cool Impact: _____ Yes No

REMARKS: CV added TR & BTEX by phone (above 11-26-18)

† Cardinal cannot accept verbal changes. Please fax written changes to 575-393-2476.

CW'S BACKHOE SERVICE

(575) 394-0421 • (575) 605-2291
 P.O. Box 1083 • Eunice, New Mexico 88231

24 HOUR SERVICE

9850

Company		Order No.	DATE
Address		Well No.	Lease
Operator	TYPE WORK PERFORMED	HOURS	RATE
			AMOUNT
			Sub Total
			Tax
			TOTAL



New Mexico Energy, Minerals and Natural Resources Department

Bill Richardson
Governor

Joanna Prukop
Cabinet Secretary
Reese Fullerton
Deputy Cabinet Secretary

Mark Fesmire
Division Director
Oil Conservation Division



January 2, 2009

Primal Energy Corporation
21021 Springbrook Plaza Dr., Suite 160
Spring, TX 77379

RE: Big Eddy Unit 132 30-015-27778
J-16-21S-29E Eddy County, New Mexico
2RP-286

Dear Operator:

This office is in receipt of your C-141 regarding the produced fluids release at this facility.

NMOCD Rule 19.15.3.116 NMAC states in part, "The responsible person must complete division approved corrective action for releases which endanger public health or the environment. Releases will be addressed in accordance with a remediation plan submitted to and approved by the division or with an abatement plan submitted in accordance with Section 19 of 19.15.1 NMAC."

A guide document intended to provide direction for remediation of soils and fresh waters contaminated as a result of leaks, spills, or releases of oilfield wastes and products is found on OCD's web site at the following link:
http://www.emnrd.state.nm.us/ocd/documents/7C_spill1.pdf

The following actions are **required** to be addressed in the **remediation plan**:

- Horizontal and vertical delineation of the spill by soil sampling. Delineation is required until contamination reaches background levels or a site specific acceptable level. Any constituent(s) of concern—to include but not limited to TPH, BTEX, and chlorides—are to be addressed in the delineation and remediation plan.
- Prepare a sketch of the site indicating where and at what depths the samples were taken.
- Submit laboratory results of sampling and the work plan proposal (plan) for remediation, removal and/or clean up of contaminants that may be present at the site.

Notify the OCD **48** hours prior to obtaining samples where analyses of samples obtained are to be submitted to the OCD. Notification is to include date and time of sample event.

Within 30 days, **on or before February 2, 2009**, completion of a remediation work plan should be finalized and submitted to the Division summarizing all actions taken or to be taken to mitigate environmental damage related to the leak, spill or release for approval.

Please be advised that NMOCD acceptance and/or approval of documents or work plans does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance and/or approval of documents or work plans do not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If I may be of further assistance with this matter or should you have any questions, please feel free to contact me.

Sincerely,

Sherry Bonham
NMOCD District II
575.748 1283 X109

