

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

JAN 08 2009

**HOBBSOCD**

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

X Initial Report  Final Report

Name of Company	Oxy USA WTP	Contact	Dusty Wilson
Address	1017 W. Stanolind Rd, Hobbs NM 88240	Telephone No.	(575) 397-8210
Facility Name	MLMU # 58	Facility Type	Well Site

Surface Owner	Jimmy Doom	Mineral Owner		Lease No.	API 30-025-27381
---------------	------------	---------------	--	-----------	------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	32	23s	37e		NW/NW			Lea

Latitude N32° 26' 05" Longitude W103° 19' 17"

**NATURE OF RELEASE**

Type of Release	OIL AND BRINE	Volume of Release	20BO, 20 BW	Volume Recovered	0 BO, 20 BW
Source of Release	3" POLY LINE SPLIT DUE TO FREEZING	Date and Hour of Occurrence	1/1/09	Date and Hour of Discovery	1/1/09 11:30 am
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	NMOCD HOBBS OFFICE, MAXI JONES		
By Whom?	CJ SUMMERS, OXY USA	Date and Hour	1/1/09 11:45 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.\*

N/A

WATER > 100

Describe Cause of Problem and Remedial Action Taken.\*

3" POLY LINE SPLIT DUE TO LINE FREEZING.

Describe Area Affected and Cleanup Action Taken.\*

REMEDiate TO NMOCD REQUIREMENTS.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Dusty L. Wilson			Approved by District Supervisor:	
Title:	HES Specialist			Approval Date:	01/12/09
E-mail Address:	dusty_wilson@oxy.com			Expiration Date:	03/13/09
Date:	1/6/09			Phone:	575-397-8210
				Conditions of Approval:	DELINTEATE / REMEDiate TO CLEAN + 1 SUBMIT FINAL C-141 BY
				Attached	<input type="checkbox"/> I RP-2044

- Attach Additional Sheets If Necessary


FGRL 0901228201

Oxy MLMU #58

W 1/4 NW 1/4 NW 1/4 Section 32 T28S R37E

Leak Point GPS N 32.36605° W 103.19197°

NT



GPS area = 6467.4 FT<sup>2</sup>

**New Mexico Office of the State Engineer  
POD Reports and Downloads**

Township: 23S Range: 37E Sections: 32

NAD27 X: Y: Zone:  Search Radius:

County:  Basin:  Number: Suffix:

Owner Name: (First) (Last)  Non-Domestic  Domestic  All

**AVERAGE DEPTH OF WATER REPORT 01/08/2009**

Bsn	Tws	Rng	Sec	Zone	X	Y	Wells	(Depth Water in Feet)		
								Min	Max	Avg
CP	23S	37E	32				1	106	106	106

Record Count: 1